

System Informacji Przestrzennej GEO-INFO Mapa (nr 1536, wyd. 25.3.1.0)

Data sporządzenia: 2026-01-23 11:26:52

Układ współrzędnych: 2000\_18 - Układ odniesienia: PL-ETRF2000-2000

Układ wysokościowy: PL-EVRF2007-NH

Baza danych: GI\_Lubliniec - (nr 5360004)

Raport przenieumerowania budynków.

Systematyki: 240703 2.0009

Lp.	Identyfikator	Stary IG5	Nowy IG5
1	3755A102897D44899C1EED32263F1CB1	240703 2.0009.AR 3.120/1.1 BUD	240703 2.0009.1 BUD
2	B54D9DB6150D4A3989151BB24FB76A05	240703 2.0009.AR 3.120/1.2 BUD	240703 2.0009.2 BUD
3	94D7716200C04E7C9BB603B4F0435560	240703 2.0009.AR 4.204/69.1 BUD	240703 2.0009.3 BUD
4	5CC095F7DE794D65A361DFD1B268B331	240703 2.0009.AR 4.204/69.2 BUD	240703 2.0009.4 BUD
5	7BCF6BA06B41467699E38FDC598A35FD	240703 2.0009.AR 4.206/69.1 BUD	240703 2.0009.5 BUD
6	CF6394B31E174C42A0AFF392AC4BCCE7	240703 2.0009.AR 4.208/69.1 BUD	240703 2.0009.6 BUD
7	AAAAC0FE0F894998929E6D9C8E4AEEA2	240703 2.0009.AR 4.216/69.1 BUD	240703 2.0009.7 BUD
8	6D6E9C604674A281A1E8EF6E67EAA8F5	240703 2.0009.AR 4.216/69.2 BUD	240703 2.0009.8 BUD
9	CD9BB8B785474CC7A2CD56BA2B84275E	240703 2.0009.AR 5.25.1 BUD	240703 2.0009.9 BUD
10	11DE4337F157405FA937C2F890F7CCD0	240703 2.0009.AR 5.25.2 BUD	240703 2.0009.10 BUD
11	A62701179E3C4FABA9D6D97EE5B3BE1C	240703 2.0009.AR 5.25.3 BUD	240703 2.0009.11 BUD
12	56353F387A0E40509326901EB051869C	240703 2.0009.AR 5.26.1 BUD	240703 2.0009.12 BUD
13	BA10E7EADA6B47C2A1F4219FF69AC001	240703 2.0009.AR 5.26.2 BUD	240703 2.0009.13 BUD
14	E98B9EE47D4543758767219713B9DC48	240703 2.0009.AR 5.62.1 BUD	240703 2.0009.14 BUD
15	4B9FAE5D953242D6BDDAB0A9E70B3DC7	240703 2.0009.AR 5.62.2 BUD	240703 2.0009.15 BUD
16	111BCE65B1674D2D80F5E0E3C57FE143	240703 2.0009.AR 5.62.3 BUD	240703 2.0009.16 BUD
17	60C79D75B90B49129911B491E27AF59B	240703 2.0009.AR 5.63.1 BUD	240703 2.0009.17 BUD
18	567F7A7E79F546149E2CAFF45A8BEF2C	240703 2.0009.AR 5.63.2 BUD	240703 2.0009.18 BUD
19	E3962D9E3B974F588EED96D1A60551D3	240703 2.0009.AR 5.64.1 BUD	240703 2.0009.19 BUD
20	B5F0EA9362C043F99B87AE62BD72D5D0	240703 2.0009.AR 5.67.1 BUD	240703 2.0009.20 BUD
21	1414FED804FF4D6A86C58838CE1AA38F	240703 2.0009.AR 5.69.1 BUD	240703 2.0009.21 BUD
22	10B7A731E9724EA68EBA8CA45A5FFCE4	240703 2.0009.AR 5.70.1 BUD	240703 2.0009.22 BUD
23	9C23AD9CE7594BDF9D51E4451F3C531C	240703 2.0009.AR 5.71.1 BUD	240703 2.0009.23 BUD
24	26421FC527F24CBA9E8BC5C62AA297A8	240703 2.0009.AR 5.71.2 BUD	240703 2.0009.24 BUD
25	B2F3F00FD6444BD0958DD4A0F4F06F64	240703 2.0009.AR 5.72.1 BUD	240703 2.0009.25 BUD
26	C8E10207A28F49749C6FAFE2130F8481	240703 2.0009.AR 5.72.2 BUD	240703 2.0009.26 BUD
27	713B304A2EB246758E344F8B7BF75268	240703 2.0009.AR 5.74.1 BUD	240703 2.0009.27 BUD
28	BBD3D611C08A431DB1FC872C07AF31F2	240703 2.0009.AR 5.74.2 BUD	240703 2.0009.28 BUD
29	6DF2262D096E460BB30032FBCEC6FBBA	240703 2.0009.AR 5.74.3 BUD	240703 2.0009.29 BUD
30	2FD5F8F6959E4618BE3EC4B48A03731C	240703 2.0009.AR 5.75.1 BUD	240703 2.0009.30 BUD
31	F484F3DBEB2040F0B0CA8086131EAC43	240703 2.0009.AR 5.75.2 BUD	240703 2.0009.31 BUD
32	B7BCF4158B3D4E7A9E497D7F61B4CE8A	240703 2.0009.AR 5.76.1 BUD	240703 2.0009.32 BUD
33	84BC44B5E13B4B3A8999CEF47950337C	240703 2.0009.AR 5.77.1 BUD	240703 2.0009.33 BUD
34	0E35722BB6094DDB9F0231CA96DB4971	240703 2.0009.AR 5.79.1 BUD	240703 2.0009.34 BUD
35	1B7146C5F45F4D139F0C46CE61A2D31C	240703 2.0009.AR 5.79.2 BUD	240703 2.0009.35 BUD
36	B425454D506740D0A9DB6F30BDD6B2F2	240703 2.0009.AR 5.87.1 BUD	240703 2.0009.36 BUD
37	E2606618DA624CF9A501F127D1143AD7	240703 2.0009.AR 5.87.2 BUD	240703 2.0009.37 BUD
38	2A7260D9772E4EB2838A753D0686D69D	240703 2.0009.AR 5.87.3 BUD	240703 2.0009.38 BUD
39	FFF4105CA06F45B99DD00EBAA5055C32	240703 2.0009.AR 5.88.1 BUD	240703 2.0009.39 BUD
40	0924DD9A49874A07B9EFF1851484E635	240703 2.0009.AR 5.88.2 BUD	240703 2.0009.40 BUD
41	CA139AFFD3DB4A2AAABBFA3DD54D14DA	240703 2.0009.AR 5.88.3 BUD	240703 2.0009.41 BUD
42	D08D2B3CD2A344CF82B20183D0967CE1	240703 2.0009.AR 5.88.4 BUD	240703 2.0009.42 BUD
43	16504076CAA5496999FDEC9111622060	240703 2.0009.AR 5.89.1 BUD	240703 2.0009.43 BUD
44	B9595508686841E6B5E4C556D7AD82FA	240703 2.0009.AR 5.89.2 BUD	240703 2.0009.44 BUD
45	D83A5D5A14074482B54947744FFBEBF6	240703 2.0009.AR 5.89.3 BUD	240703 2.0009.45 BUD
46	D79BBDE1996047ACA40EE60BDD6BB9B7	240703 2.0009.AR 5.96.1 BUD	240703 2.0009.46 BUD
47	AF721C9FFADC4BE4BD5AB7E8AB6D5146	240703 2.0009.AR 5.96.2 BUD	240703 2.0009.47 BUD
48	9DEE78E167E34AAEA322B3F0C8B01E4A	240703 2.0009.AR 5.96.3 BUD	240703 2.0009.48 BUD
49	8C469763644642B4A70DD660A979611B	240703 2.0009.AR 5.103.1 BUD	240703 2.0009.49 BUD
50	506EAE0A74A341098D6386D12ABBE53B	240703 2.0009.AR 5.103.2 BUD	240703 2.0009.50 BUD
51	B4307AE099EB41FCAA7C0C93029BC012	240703 2.0009.AR 5.103.3 BUD	240703 2.0009.51 BUD
52	3687D92A1DE447ABA64227B3D3E8FA15	240703 2.0009.AR 5.103.4 BUD	240703 2.0009.52 BUD
53	715571F1D9AD4E93B6F695400C12C0FD	240703 2.0009.AR 5.104.1 BUD	240703 2.0009.53 BUD
54	074DA13D114C48D9841C17F6562A3EBB	240703 2.0009.AR 5.105.1 BUD	240703 2.0009.54 BUD
55	622F08474DA941889799500DFD25E4C9	240703 2.0009.AR 5.107.1 BUD	240703 2.0009.55 BUD
56	6B4AC00CA2BA488DA1491C4BEDE7EBE7	240703 2.0009.AR 5.107.2 BUD	240703 2.0009.56 BUD
57	867D02AB9C6747FF91145E9C45B11375	240703 2.0009.AR 5.124/95.1 BUD	240703 2.0009.57 BUD

58	E16430A0415B4D1FBC4B708FB1FE2C4F	240703 2.0009.AR 5.124/95.2 BUD	240703 2.0009.58 BUD
59	292FBC1E0D7F47DEB2020E55840DFCE5	240703 2.0009.AR 5.124/95.3 BUD	240703 2.0009.59 BUD
60	094A966E15F149C486D3249FD5BA404F	240703 2.0009.AR 5.138/106.1 BUD	240703 2.0009.60 BUD
61	4C5F5D31DD294CCAA7E12F40E69DE22F	240703 2.0009.AR 5.138/106.2 BUD	240703 2.0009.61 BUD
62	594083D0F14745F082ACEF7B3D8B7727	240703 2.0009.AR 5.139/111.1 BUD	240703 2.0009.62 BUD
63	729BDD7882B54B1A8F9030531139B98C	240703 2.0009.AR 5.139/111.2 BUD	240703 2.0009.63 BUD
64	AAC6F21A365D4B478E735C4901BD5ABD	240703 2.0009.AR 5.145/110.1 BUD	240703 2.0009.64 BUD
65	D16015938ECC4217B020D2A19E9ED2F2	240703 2.0009.AR 5.146/112.1 BUD	240703 2.0009.65 BUD
66	8A5CE1378C214F34BED4E790754B8777	240703 2.0009.AR 5.165/21.1 BUD	240703 2.0009.66 BUD
67	9F6F937BC94F49DFB14D9F1781116BDD	240703 2.0009.AR 5.165/21.2 BUD	240703 2.0009.67 BUD
68	BDCF99BDD4CA491599F9C6E12E6A4A16	240703 2.0009.AR 5.165/21.3 BUD	240703 2.0009.68 BUD
69	E5536288A7454A0A931C853668BE27BE	240703 2.0009.AR 5.165/21.4 BUD	240703 2.0009.69 BUD
70	CAF55BD39A16451E9D6043E168E84E25	240703 2.0009.AR 5.165/21.5 BUD	240703 2.0009.70 BUD
71	D72B4BC272D24591A05ABAE3619E03F5	240703 2.0009.AR 5.176/73.1 BUD	240703 2.0009.71 BUD
72	17CBEEAFA72448C1AB0375A49B5C9D35	240703 2.0009.AR 5.176/73.2 BUD	240703 2.0009.72 BUD
73	B69F449D8C88447FB3539A3C4E49F9D7	240703 2.0009.AR 5.177/73.1 BUD	240703 2.0009.73 BUD
74	69C905E7C81B4CF989BDBB68AABE7038	240703 2.0009.AR 5.177/73.2 BUD	240703 2.0009.74 BUD
75	D82801841B92455F8F18583B9FA686B9	240703 2.0009.AR 5.177/73.3 BUD	240703 2.0009.75 BUD
76	8BEBEC23249E4D3698D05E373104945A	240703 2.0009.AR 5.178/73.1 BUD	240703 2.0009.76 BUD
77	5F29CBB5940C452D9ABBCA5C9881ED2E	240703 2.0009.AR 5.211/92.1 BUD	240703 2.0009.77 BUD
78	0BDE00F55DFF4CB68CEB3082AD05E24D	240703 2.0009.AR 5.211/92.2 BUD	240703 2.0009.78 BUD
79	6542B4063DCB498E853EA285101F58B9	240703 2.0009.AR 5.213/61.1 BUD	240703 2.0009.79 BUD
80	C5B741E189504ABB99D304099A5117C6	240703 2.0009.AR 5.213/61.2 BUD	240703 2.0009.80 BUD
81	570690D6B9444D3893B8390B27746076	240703 2.0009.AR 5.250/3.1 BUD	240703 2.0009.81 BUD
82	569617574F624082A2E39A2D9B569E20	240703 2.0009.AR 5.250/3.2 BUD	240703 2.0009.82 BUD
83	E252E1DC1A20490A85B2CB600450DBAB	240703 2.0009.AR 5.250/3.3 BUD	240703 2.0009.83 BUD
84	D9D2950A249F415B86343BAC1A4225AE	240703 2.0009.AR 5.253/3.1 BUD	240703 2.0009.84 BUD
85	9B66B191CDEE478E8F7242D2CE6CE704	240703 2.0009.AR 5.262/83.1 BUD	240703 2.0009.85 BUD
86	3F29311CF054444891ADCF57BC1F90AD	240703 2.0009.AR 5.262/83.2 BUD	240703 2.0009.86 BUD
87	C0E26C2E2B2249C99EDCB42EC7BE67BD	240703 2.0009.AR 5.262/83.3 BUD	240703 2.0009.87 BUD
88	882AF16252A24A3AAA44B0A9FF9FE342	240703 2.0009.AR 5.264/3.1 BUD	240703 2.0009.88 BUD
89	F8F79CECBAF443B19E815470B55DD1AB	240703 2.0009.AR 5.267/3.1 BUD	240703 2.0009.89 BUD
90	53FEA83F506B4AEF91F81EB19902CEC4	240703 2.0009.AR 5.267/3.2 BUD	240703 2.0009.90 BUD
91	0B4CBC1D8E424FAEBA515B56F2C8E210	240703 2.0009.AR 5.273/81.2 BUD	240703 2.0009.91 BUD
92	59207487CCDB47A3AB806EE94A5B4390	240703 2.0009.AR 5.274/81.1 BUD	240703 2.0009.92 BUD
93	72A383186F964BEBAC72629A3FF7E0B6	240703 2.0009.AR 5.275/78.1 BUD	240703 2.0009.93 BUD
94	F5AF7931FFDD48CCA0C8390734D0807	240703 2.0009.AR 5.279/83.1 BUD	240703 2.0009.94 BUD
95	07B289E42B1440E7B1A2D334B9B1EA2F	240703 2.0009.AR 6.54.1 BUD	240703 2.0009.95 BUD
96	029879BF4984405ABC656780056E8ECE	240703 2.0009.AR 6.60.1 BUD	240703 2.0009.96 BUD
97	D5BCC913EA784F5BAB86D79CD5B89173	240703 2.0009.AR 6.75.1 BUD	240703 2.0009.97 BUD
98	EA280A2A8E3B4EF9BF283966FAC0D683	240703 2.0009.AR 6.75.2 BUD	240703 2.0009.98 BUD
99	82B4F8A535254421B5E4A02A0BD9935F	240703 2.0009.AR 6.76.1 BUD	240703 2.0009.99 BUD
100	13B01792B9104DE3AA481E7F19C21EE1	240703 2.0009.AR 6.77.1 BUD	240703 2.0009.100 BUD
101	D0148E11538F49F1BD9CA10F845258F6	240703 2.0009.AR 6.78.1 BUD	240703 2.0009.101 BUD
102	C1174488388E49CBA84E2897AE4DA0BF	240703 2.0009.AR 6.78.2 BUD	240703 2.0009.102 BUD
103	C2AD991C9C964A98BE2E33CEFF39CD3E	240703 2.0009.AR 6.78.3 BUD	240703 2.0009.103 BUD
104	34708F0B913D4382BD489E259567A08A	240703 2.0009.AR 6.85.1 BUD	240703 2.0009.104 BUD
105	81B22CA24B424554BCCAAA9E947C05ED	240703 2.0009.AR 6.90.1 BUD	240703 2.0009.105 BUD
106	F3C2E3716E00471D97A45F6F67C68836	240703 2.0009.AR 6.90.2 BUD	240703 2.0009.106 BUD
107	5F98C63DCE4C444B8441E1191E18F055	240703 2.0009.AR 6.92.1 BUD	240703 2.0009.107 BUD
108	874E43713CB0463AA5D4B4A8A2CC30C3	240703 2.0009.AR 6.98.1 BUD	240703 2.0009.108 BUD
109	91211EA1682E4ABDBC80FFAEC69C11E9	240703 2.0009.AR 6.98.2 BUD	240703 2.0009.109 BUD
110	EF416C48D7114DF8B84AAF582647612D	240703 2.0009.AR 6.98.3 BUD	240703 2.0009.110 BUD
111	6D7F19008FAC41979E5BCB7CF9C91F6B	240703 2.0009.AR 6.98.4 BUD	240703 2.0009.111 BUD
112	1D4EC2BF2DD14A77BC4C7664D7BB2A10	240703 2.0009.AR 6.98.5 BUD	240703 2.0009.112 BUD
113	DFBE9F43FD3B4EA3BF03B7734D165169	240703 2.0009.AR 6.98.6 BUD	240703 2.0009.113 BUD
114	243F92CC327B4963B4EC3970C6FC2B6A	240703 2.0009.AR 6.100.1 BUD	240703 2.0009.114 BUD
115	D5F96E6EAFAB40839FC0B9AD1530F8B3	240703 2.0009.AR 6.101.1 BUD	240703 2.0009.115 BUD
116	1CDF7587FFB845E1AE1E29C7441E05AF	240703 2.0009.AR 6.102.1 BUD	240703 2.0009.116 BUD
117	E6B663C3EA834D66894BE96447FAB862	240703 2.0009.AR 6.102.2 BUD	240703 2.0009.117 BUD
118	2DCDE5E042954AF0995ABA8316478351	240703 2.0009.AR 6.103.1 BUD	240703 2.0009.118 BUD
119	88E094C638F34DDFA73AAE296CAD2256	240703 2.0009.AR 6.104.1 BUD	240703 2.0009.119 BUD
120	E6B5DEDD626248B98521DE21EF6E6CE9	240703 2.0009.AR 6.104.2 BUD	240703 2.0009.120 BUD
121	0CE509E2C59D427D892072A8EB84DB65	240703 2.0009.AR 6.118.1 BUD	240703 2.0009.121 BUD
122	904C1183A6924CB9809CE018F136318E	240703 2.0009.AR 6.119.1 BUD	240703 2.0009.122 BUD
123	B29F9BC88E374E56BAD9517515FD7DFD	240703 2.0009.AR 6.119.2 BUD	240703 2.0009.123 BUD

124	D56407E5E9084333A7546D7FA915F960	240703 2.0009.AR 6.120.1 BUD	240703 2.0009.124 BUD
125	DA7D9152DF2346BBB4FDBD189FF65F8E	240703 2.0009.AR 6.120.2 BUD	240703 2.0009.125 BUD
126	35D841FCAB9C4CD99504391FDCCD258DD	240703 2.0009.AR 6.121.1 BUD	240703 2.0009.126 BUD
127	E08E19950E704ACAB42488B29CB12DC3	240703 2.0009.AR 6.121.2 BUD	240703 2.0009.127 BUD
128	1DDC17475CA242308BFB42D507E18623	240703 2.0009.AR 6.121.3 BUD	240703 2.0009.128 BUD
129	1005B84EA908481AB037D0117616B582	240703 2.0009.AR 6.122.1 BUD	240703 2.0009.129 BUD
130	E8D0360843984D078DC3278EFD618D0C	240703 2.0009.AR 6.125.1 BUD	240703 2.0009.130 BUD
131	F90233B471454C95998583C662CF697B	240703 2.0009.AR 6.125.2 BUD	240703 2.0009.131 BUD
132	95EA84B5C9214591870ED8C858D5F7D2	240703 2.0009.AR 6.125.3 BUD	240703 2.0009.132 BUD
133	AE8A8F510A7641ECACC4A13D2FD00870	240703 2.0009.AR 6.125.4 BUD	240703 2.0009.133 BUD
134	2E2393399D7646658AF6126623E47EC2	240703 2.0009.AR 6.128.1 BUD	240703 2.0009.134 BUD
135	904151258BB24810B10B77AC880B7E7C	240703 2.0009.AR 6.130.1 BUD	240703 2.0009.135 BUD
136	8F74C2D067C347EFB3568C63D9855B38	240703 2.0009.AR 6.130.2 BUD	240703 2.0009.136 BUD
137	2076364400DE4C95B1C57F436A8794EC	240703 2.0009.AR 6.130.3 BUD	240703 2.0009.137 BUD
138	01084896D0BD49DDA6796E4DF433EA40	240703 2.0009.AR 6.210.1 BUD	240703 2.0009.138 BUD
139	6125FB0C3D574A15A309C9410C470184	240703 2.0009.AR 6.213.1 BUD	240703 2.0009.139 BUD
140	FBAED8BC910C45C8A39C30F83B2A5F31	240703 2.0009.AR 6.213.2 BUD	240703 2.0009.140 BUD
141	88A4999B430A47FAAB45CE4EF0E61544	240703 2.0009.AR 6.215.1 BUD	240703 2.0009.141 BUD
142	A71EC12ED8324612A10704218067DF47	240703 2.0009.AR 6.217.1 BUD	240703 2.0009.142 BUD
143	5BE50D6302D148B3A614CFEB5219BFB4	240703 2.0009.AR 6.228.1 BUD	240703 2.0009.143 BUD
144	3A146E3587884F678A2B838E9E8613D5	240703 2.0009.AR 6.230.1 BUD	240703 2.0009.144 BUD
145	6343BF97938C485687E93695CE9E322B	240703 2.0009.AR 6.230.2 BUD	240703 2.0009.145 BUD
146	85E76A2B0EE64F1B94818C735BB0904A	240703 2.0009.AR 6.297/70.1 BUD	240703 2.0009.146 BUD
147	5AFEDED972DF4DBCACE1CC6EC4665E08	240703 2.0009.AR 6.297/70.2 BUD	240703 2.0009.147 BUD
148	A2D699EE922141DA968B0E9475DAA569	240703 2.0009.AR 6.297/70.3 BUD	240703 2.0009.148 BUD
149	5387E5CC109F4719A0C9B4C44812D0AC	240703 2.0009.AR 6.319/89.1 BUD	240703 2.0009.149 BUD
150	E1BB53F26B9244F19D51776FBB9A030D	240703 2.0009.AR 6.340/48.1 BUD	240703 2.0009.150 BUD
151	FFD08E51289846AE8CB47D3E8EB6072B	240703 2.0009.AR 6.343/87.1 BUD	240703 2.0009.151 BUD
152	236B766D50334E5893FA4D45684667D8	240703 2.0009.AR 6.343/87.2 BUD	240703 2.0009.152 BUD
153	EE0914D06F644FE2B864FBE0F71ABBC3	240703 2.0009.AR 6.343/87.3 BUD	240703 2.0009.153 BUD
154	6B6D7A8F278C42C28C91DEEB21FC4473	240703 2.0009.AR 6.354/53.1 BUD	240703 2.0009.154 BUD
155	236B2345AD814102883C9236BE813FCF	240703 2.0009.AR 6.399/48.1 BUD	240703 2.0009.155 BUD
156	525AB12C33EA4ABDB159A92100682668	240703 2.0009.AR 6.399/48.2 BUD	240703 2.0009.156 BUD
157	830D5F7D1B0A486A9AC8B56DF4EDB525	240703 2.0009.AR 6.410/107.1 BUD	240703 2.0009.157 BUD
158	2CD1DB687E35405F9BF3C18A1C50E802	240703 2.0009.AR 6.459/48.1 BUD	240703 2.0009.158 BUD
159	121AB6DE3C8A4345ABC12BFA5A13310E	240703 2.0009.AR 6.459/48.2 BUD	240703 2.0009.159 BUD
160	7CDCB33A40644400AF6BB04DCF721A75	240703 2.0009.AR 6.459/48.3 BUD	240703 2.0009.160 BUD
161	C61916DE519C4DC0AF3B80477F06192E	240703 2.0009.AR 6.460/48.1 BUD	240703 2.0009.161 BUD
162	6A0EEEEBE2C349C0907E464340851B42	240703 2.0009.AR 6.462/65.1 BUD	240703 2.0009.162 BUD
163	4CDD1D17DAF24A8F9C9373FB69A91E63	240703 2.0009.AR 6.462/65.2 BUD	240703 2.0009.163 BUD
164	2037C2F2260247848EDFC58F25255A98	240703 2.0009.AR 6.463/65.1 BUD	240703 2.0009.164 BUD
165	B809CF5F67EE490C8B43ABFF6DDCAA68	240703 2.0009.AR 6.463/65.2 BUD	240703 2.0009.165 BUD
166	197462704AD14A8784FE739C93CB9CDA	240703 2.0009.AR 6.473/48.1 BUD	240703 2.0009.166 BUD
167	2D82F217E13D4BD9A71F0F794B02F510	240703 2.0009.AR 6.473/48.2 BUD	240703 2.0009.167 BUD
168	ADF37FFC05E04AD995FA24BC491D5534	240703 2.0009.AR 6.473/48.3 BUD	240703 2.0009.168 BUD
169	D6F12ADCFCDF4E408C1A25C22C1601DF	240703 2.0009.AR 6.473/48.4 BUD	240703 2.0009.169 BUD
170	7CC65F6CD8F140328AE4EA3C70075ED0	240703 2.0009.AR 6.474/48.1 BUD	240703 2.0009.170 BUD
171	63779201501049EF97E49ED2851F9D6D	240703 2.0009.AR 6.476/48.1 BUD	240703 2.0009.171 BUD
172	1110FC018278403C80A18DDA887A7CF1	240703 2.0009.AR 6.476/48.2 BUD	240703 2.0009.172 BUD
173	9E0ABF4FACB4441E9C954269420D7588	240703 2.0009.AR 6.476/48.3 BUD	240703 2.0009.173 BUD
174	2F8ACFB3E5124F21BB67BAB883C263E1	240703 2.0009.AR 6.476/48.4 BUD	240703 2.0009.174 BUD
175	7BD4C6DA93C944BEAD8C339BFEBF57FC	240703 2.0009.AR 6.477/48.1 BUD	240703 2.0009.175 BUD
176	876E0FD50305477396F4B05A55F90AB7	240703 2.0009.AR 6.480/48.1 BUD	240703 2.0009.176 BUD
177	C1A4F832F0AA4579A30AFB29133F2B00	240703 2.0009.AR 6.483/129.1 BUD	240703 2.0009.177 BUD
178	7E657C77F79B455EB2B5713FFC6B139D	240703 2.0009.AR 6.483/129.2 BUD	240703 2.0009.178 BUD
179	FD4C0E0E46154F4BB1795C4A2557FD4E	240703 2.0009.AR 6.483/129.3 BUD	240703 2.0009.179 BUD
180	5C528BE9BE754214BCEBCCE5E0C50FF2	240703 2.0009.AR 6.488/226.1 BUD	240703 2.0009.180 BUD
181	E1969E16D53540DC9B3D826049297278	240703 2.0009.AR 6.488/226.2 BUD	240703 2.0009.181 BUD
182	8F17CA7092214BA0B829C3B3C9B44F62	240703 2.0009.AR 6.489/225.1 BUD	240703 2.0009.182 BUD
183	FE2DA345175043D7BE247B15BE9EDC2C	240703 2.0009.AR 6.489/225.2 BUD	240703 2.0009.183 BUD
184	C976349416764532B8F7A7E3034E87F8	240703 2.0009.AR 6.489/225.3 BUD	240703 2.0009.184 BUD
185	C04AB6E3CD4A430484D2989FF7FFCAC1	240703 2.0009.AR 6.489/225.4 BUD	240703 2.0009.185 BUD
186	82453369A05A42D0A00D4DCF30B9D250	240703 2.0009.AR 6.494/231.1 BUD	240703 2.0009.186 BUD
187	84DC7E1BCC61444B9F0457C21AB0152A	240703 2.0009.AR 6.494/231.2 BUD	240703 2.0009.187 BUD
188	CFAC22BB61EA465187127721D835BB39	240703 2.0009.AR 6.499/48.1 BUD	240703 2.0009.188 BUD
189	A7FF08AD352B4BF398132C60AAC092CA	240703 2.0009.AR 6.500/48.1 BUD	240703 2.0009.189 BUD

190	75872A10ABA944E489C12723110BFB74	240703	2.0009.AR	6.500/48.2	BUD	240703	2.0009.190	BUD
191	297DFABD364B4C24B31749BA6FA03455	240703	2.0009.AR	6.505/51.1	BUD	240703	2.0009.191	BUD
192	A4745B967AA44E6391790B75566E47D4	240703	2.0009.AR	6.505/51.2	BUD	240703	2.0009.192	BUD
193	9B47D679BE964A5380D738954637DCFC	240703	2.0009.AR	6.505/51.3	BUD	240703	2.0009.193	BUD
194	7BCC21DB59B24B999A0D48CB5855F465	240703	2.0009.AR	6.506/232.1	BUD	240703	2.0009.194	BUD
195	908138B0E8DC4F81BE57E6C2FD37FB16	240703	2.0009.AR	6.509/51.1	BUD	240703	2.0009.195	BUD
196	491D9A36F9AA421DAA48B240A0C519BF	240703	2.0009.AR	6.509/51.2	BUD	240703	2.0009.196	BUD
197	86939CF592D84EC8B70303C244B0BA67	240703	2.0009.AR	6.510/51.1	BUD	240703	2.0009.197	BUD
198	63F9B8BAA5AC4A6C81ACEDA3A2A0B98A	240703	2.0009.AR	6.522/63.1	BUD	240703	2.0009.198	BUD
199	D8590F42612C43D6AFF9114176D5856B	240703	2.0009.AR	7.3.1	BUD	240703	2.0009.199	BUD
200	F26377861A5F45D0B051300452AF3443	240703	2.0009.AR	7.5.1	BUD	240703	2.0009.200	BUD
201	DB51847153FD47FD85BA06F756584550	240703	2.0009.AR	7.5.2	BUD	240703	2.0009.201	BUD
202	196E5AC57A624B14B043B4EAA9BADF67	240703	2.0009.AR	7.6.1	BUD	240703	2.0009.202	BUD
203	3FB04686F8C546399B7CC7A4CCDC7706	240703	2.0009.AR	7.6.2	BUD	240703	2.0009.203	BUD
204	D5084EF65EC340BE8A4100FBC540BE14	240703	2.0009.AR	7.9.1	BUD	240703	2.0009.204	BUD
205	A215B3B5C81B43DFBC2686FC46EEE6D5	240703	2.0009.AR	7.10.1	BUD	240703	2.0009.205	BUD
206	117C08C7B71D464A8593481D9F351114	240703	2.0009.AR	7.11.1	BUD	240703	2.0009.206	BUD
207	B6B8B2FA255C4577A2093F8F1F8E95BB	240703	2.0009.AR	7.11.2	BUD	240703	2.0009.207	BUD
208	489393CB71E6426CB8B807B50760D7B8	240703	2.0009.AR	7.11.3	BUD	240703	2.0009.208	BUD
209	F5526549193B40BB8EAC4F8C9B5FDD26	240703	2.0009.AR	7.11.4	BUD	240703	2.0009.209	BUD
210	38169F75FDA74A1C81EAE015DCD50102	240703	2.0009.AR	7.28.1	BUD	240703	2.0009.210	BUD
211	C944BC7380154447803EE2DFA14F45D9	240703	2.0009.AR	7.29.1	BUD	240703	2.0009.211	BUD
212	I31C1F7FD48D43EF9AF6FC1D0F038FCF	240703	2.0009.AR	7.30.1	BUD	240703	2.0009.212	BUD
213	I132BE0803D34F559A9F1A0CCDDDDACA	240703	2.0009.AR	7.128.1	BUD	240703	2.0009.213	BUD
214	B7CA627C1C404B739883E276CF5FD0AF	240703	2.0009.AR	7.129.1	BUD	240703	2.0009.214	BUD
215	888125ACF3BF4154BA3DCD0EE826DED6	240703	2.0009.AR	7.144.1	BUD	240703	2.0009.215	BUD
216	7D7301870A534057A959E90D3D396603	240703	2.0009.AR	7.144.2	BUD	240703	2.0009.216	BUD
217	2B04133CDEC3432FBA3F896267D188A6	240703	2.0009.AR	7.145.1	BUD	240703	2.0009.217	BUD
218	F4DB43C9CAA4429D88C6BEF7DA0C67C2	240703	2.0009.AR	7.145.2	BUD	240703	2.0009.218	BUD
219	E09C88754129446292F15AD2E5B2A919	240703	2.0009.AR	7.145.3	BUD	240703	2.0009.219	BUD
220	4953212A5CD94DE083C33D90E9DCD099	240703	2.0009.AR	7.145.4	BUD	240703	2.0009.220	BUD
221	D972AA9FEA4743D2AAD948ABEA3D4A4B	240703	2.0009.AR	7.146.1	BUD	240703	2.0009.221	BUD
222	4BDD6A8D7E234AF78FB55D1D4C0E1185	240703	2.0009.AR	7.146.2	BUD	240703	2.0009.222	BUD
223	F4227F37B0BA47D1B63364FD870F6597	240703	2.0009.AR	7.146.3	BUD	240703	2.0009.223	BUD
224	7DCCD9DD7F3741B0A403D620E72CAF91	240703	2.0009.AR	7.147.1	BUD	240703	2.0009.224	BUD
225	041FD7E153C7497F8DF51ADEE1EC4F38	240703	2.0009.AR	7.147.2	BUD	240703	2.0009.225	BUD
226	4577F28432044889BB18A0A465A95BCD	240703	2.0009.AR	7.149.1	BUD	240703	2.0009.226	BUD
227	AFA800C77DE4C431A0AA1CA8BC4D5EB8	240703	2.0009.AR	7.149.2	BUD	240703	2.0009.227	BUD
228	0060D53470904E91B75FB223A61D322E	240703	2.0009.AR	7.155.1	BUD	240703	2.0009.228	BUD
229	FD90459FC11645DA9BE81FFD5BFB48FA	240703	2.0009.AR	7.155.2	BUD	240703	2.0009.229	BUD
230	B8F9429E13B24333A186FF3176B5EED2	240703	2.0009.AR	7.155.3	BUD	240703	2.0009.230	BUD
231	9D6763EA63D8436DBF116F9952061379	240703	2.0009.AR	7.156.1	BUD	240703	2.0009.231	BUD
232	103E87C3B9794454A44E96A111693550	240703	2.0009.AR	7.156.2	BUD	240703	2.0009.232	BUD
233	A162AAE4E74E4A9CB46BDF78792A9691	240703	2.0009.AR	7.156.3	BUD	240703	2.0009.233	BUD
234	C6D8B76BDA564CEFA65A34C49B6D53A7	240703	2.0009.AR	7.156.4	BUD	240703	2.0009.234	BUD
235	E9A806AAE8CF4E8CA0BE39DF2EAA4C90	240703	2.0009.AR	7.157.1	BUD	240703	2.0009.235	BUD
236	D91B5B8E8BF74162AC8FF12D19A4B372	240703	2.0009.AR	7.157.2	BUD	240703	2.0009.236	BUD
237	152FACAC924841209459A2A06731C8F2	240703	2.0009.AR	7.159.1	BUD	240703	2.0009.237	BUD
238	7CC8FE45583E464A9321BC3832E76FAB	240703	2.0009.AR	7.159.2	BUD	240703	2.0009.238	BUD
239	533B42F880FA40E4A1ED17A2E6EFC257	240703	2.0009.AR	7.159.3	BUD	240703	2.0009.239	BUD
240	607AC0647ACD42D6B5EA80B66152BC3F	240703	2.0009.AR	7.159.4	BUD	240703	2.0009.240	BUD
241	C4DFB33602914983B1393F98F5A89176	240703	2.0009.AR	7.161.1	BUD	240703	2.0009.241	BUD
242	8C08F23A3EA04D5A89A84FB7E4F5BD49	240703	2.0009.AR	7.161.2	BUD	240703	2.0009.242	BUD
243	9DBC5599CBE94E3BA24C60CFD07EB719	240703	2.0009.AR	7.162.1	BUD	240703	2.0009.243	BUD
244	E10D6E061BD240CD94121CA6370EEF73	240703	2.0009.AR	7.166.1	BUD	240703	2.0009.244	BUD
245	ABFFEA4DE9244BBF8F9C479BF4435E26	240703	2.0009.AR	7.166.2	BUD	240703	2.0009.245	BUD
246	37481DE402B44965B4973ABE85768E01	240703	2.0009.AR	7.166.3	BUD	240703	2.0009.246	BUD
247	023E2F7D7E0E411DBAD801DB3D304D01	240703	2.0009.AR	7.166.4	BUD	240703	2.0009.247	BUD
248	ABC0D46C40614A87A653BAFA71AC8F6C	240703	2.0009.AR	7.170.1	BUD	240703	2.0009.248	BUD
249	FB724DAFF1FF4264A7560D2A8FAEEF5B	240703	2.0009.AR	7.170.2	BUD	240703	2.0009.249	BUD
250	8D0A7E467A274EF18BF507FDB304D827	240703	2.0009.AR	7.170.3	BUD	240703	2.0009.250	BUD
251	7DE02E1694D54F88937A5094CFB98376	240703	2.0009.AR	7.170.4	BUD	240703	2.0009.251	BUD
252	86E963EC67574AEBBFCECEC1387E52595	240703	2.0009.AR	7.252/123.1	BUD	240703	2.0009.252	BUD
253	7A9D65B71EEF4C7E8A028BC360D7DA6A	240703	2.0009.AR	7.253/121.1	BUD	240703	2.0009.253	BUD
254	ED21F0AEA34941CB808F959883269072	240703	2.0009.AR	7.253/121.2	BUD	240703	2.0009.254	BUD
255	53706BF225484F44A88E834C40DE910C	240703	2.0009.AR	7.254/165.1	BUD	240703	2.0009.255	BUD

256	FB40E864363A49859632BFE1BD99FA56	240703	2.0009.AR	7.254/165.2	BUD	240703	2.0009.256	BUD
257	BBDBF47B723A45368A943C7580D94CF9	240703	2.0009.AR	7.254/165.3	BUD	240703	2.0009.257	BUD
258	7919E37BD21849969669EEEE07DB35F4B	240703	2.0009.AR	7.254/165.4	BUD	240703	2.0009.258	BUD
259	E714DAD7915B4C618ED4CA915E7A1F21	240703	2.0009.AR	7.255/165.1	BUD	240703	2.0009.259	BUD
260	8ECB6206B1624FFE86B5E4863FA47FB6	240703	2.0009.AR	7.255/165.2	BUD	240703	2.0009.260	BUD
261	2D3327DD7F014C888D7F93FCA9BA06EB	240703	2.0009.AR	7.255/165.3	BUD	240703	2.0009.261	BUD
262	32FDF2C11C21404AAF88C3BE4E977403	240703	2.0009.AR	7.255/165.4	BUD	240703	2.0009.262	BUD
263	388FCB881ACE4642A422AC41BAC0DA4E	240703	2.0009.AR	7.257/2.1	BUD	240703	2.0009.263	BUD
264	F3FF509FBA914A34894AAB3E2DABA1D3	240703	2.0009.AR	7.257/2.2	BUD	240703	2.0009.264	BUD
265	BAA22B20536547FC929E7093E6B1F584	240703	2.0009.AR	7.258/2.1	BUD	240703	2.0009.265	BUD
266	61A994000B7F41728DA3CFA1A9E2C3D6	240703	2.0009.AR	7.258/2.2	BUD	240703	2.0009.266	BUD
267	A4BD3DCA8032422599105702400CC89E	240703	2.0009.AR	7.293/15.1	BUD	240703	2.0009.267	BUD
268	BADEC2EDD7A34A23A65BC6FB86BF56D3	240703	2.0009.AR	7.317/150.1	BUD	240703	2.0009.268	BUD
269	4E1BE4D345C0437D2EBB80FA8AA1AE2219	240703	2.0009.AR	7.317/150.2	BUD	240703	2.0009.269	BUD
270	109FEB031B6A4D2EBB80FA8AA1AE2219	240703	2.0009.AR	7.317/150.3	BUD	240703	2.0009.270	BUD
271	23BB986A236A42C9894A1D14791DF503	240703	2.0009.AR	7.317/150.4	BUD	240703	2.0009.271	BUD
272	34129012C3A74DEFB7A41EA28F0F55FE	240703	2.0009.AR	7.317/150.5	BUD	240703	2.0009.272	BUD
273	3F972079C61B4ABDA2F94B5F8328F720	240703	2.0009.AR	7.317/150.6	BUD	240703	2.0009.273	BUD
274	D29CC18C1B0B4A0E83238D17F9125AFE	240703	2.0009.AR	7.319/150.1	BUD	240703	2.0009.274	BUD
275	D1703BDBD9B9496B996C2DC3B29D97AE	240703	2.0009.AR	7.319/150.2	BUD	240703	2.0009.275	BUD
276	E7CD70CFC5E64FBA8908C5DDD94BF0EE	240703	2.0009.AR	7.321/153.1	BUD	240703	2.0009.276	BUD
277	38393E99362A4AF5991EF7F03CAFEB4C	240703	2.0009.AR	7.326/123.1	BUD	240703	2.0009.277	BUD
278	3153BDF479AB48E6A155504B5420A303	240703	2.0009.AR	7.326/123.3	BUD	240703	2.0009.278	BUD
279	62BA124AE5654EAE04F2E5CDD49D5C0	240703	2.0009.AR	7.327/123.1	BUD	240703	2.0009.279	BUD
280	446F56C1D886494A8F061EC783DC77AB	240703	2.0009.AR	7.327/123.2	BUD	240703	2.0009.280	BUD
281	0795F1BA47A5496790FBC780F58873F9	240703	2.0009.AR	7.327/123.3	BUD	240703	2.0009.281	BUD
282	145DF23FFBD249FBAA1480EBCBAC4DFD	240703	2.0009.AR	7.327/123.4	BUD	240703	2.0009.282	BUD
283	1FE9082FE39B4F38B7DBF1B23E37F7BD	240703	2.0009.AR	7.327/123.5	BUD	240703	2.0009.283	BUD
284	D16A0FCD4ADA4A639309838F03762EA6	240703	2.0009.AR	7.328/123.5	BUD	240703	2.0009.284	BUD
285	F2795A30C07C47C19A46A46374BA545B	240703	2.0009.AR	7.329/123.1	BUD	240703	2.0009.285	BUD
286	61F38FAAC1074A84B51E5EC0F5F385F5	240703	2.0009.AR	7.329/123.2	BUD	240703	2.0009.286	BUD
287	60F5A0925BD04A33BE8D552174969B78	240703	2.0009.AR	7.329/123.3	BUD	240703	2.0009.287	BUD
288	0456F61710314C649B9E13708A609842	240703	2.0009.AR	7.329/123.4	BUD	240703	2.0009.288	BUD
289	F9BB0169E9244052B41D2C7E1F475239	240703	2.0009.AR	7.337/132.1	BUD	240703	2.0009.289	BUD
290	264ED03401684234AD759738F1CC5EC6	240703	2.0009.AR	7.337/132.2	BUD	240703	2.0009.290	BUD
291	7018A5B3385B48D1B28A15D1D3C619B4	240703	2.0009.AR	7.338/132.1	BUD	240703	2.0009.291	BUD
292	18401FAB52A74FC0A7C901FD08F6A177	240703	2.0009.AR	7.339/152.1	BUD	240703	2.0009.292	BUD
293	7FB0745E32B54A7D94D3E9551283C1BF	240703	2.0009.AR	7.340/152.1	BUD	240703	2.0009.293	BUD
294	6C11CC853537416694874BDB6664E435	240703	2.0009.AR	7.340/152.2	BUD	240703	2.0009.294	BUD
295	90473C2EED9A4C229264BC55D01C2D23	240703	2.0009.AR	7.340/152.3	BUD	240703	2.0009.295	BUD
296	999B7B578F564B218DADE6652504BB04	240703	2.0009.AR	7.340/152.4	BUD	240703	2.0009.296	BUD
297	B8189FF098B840DAAB179099471C6D85	240703	2.0009.AR	7.340/152.5	BUD	240703	2.0009.297	BUD
298	5E20FEA6FBAD4D6F98942BAE8E2B3FBF	240703	2.0009.AR	7.355/143.2	BUD	240703	2.0009.298	BUD
299	69A9B8F13F5440B7BB4BD3DB0018A011	240703	2.0009.AR	7.355/143.3	BUD	240703	2.0009.299	BUD
300	D8CAEB854D2F488284BA3CC20ACC1B90	240703	2.0009.AR	7.372/125.1	BUD	240703	2.0009.300	BUD
301	I41C20228821408D874452D27AE4C4A3	240703	2.0009.AR	7.372/125.2	BUD	240703	2.0009.301	BUD
302	ED4AEAF797684D4F88A25656166426B9	240703	2.0009.AR	7.372/125.3	BUD	240703	2.0009.302	BUD
303	0D9B26EA249F47719858FDBFFA91CE87	240703	2.0009.AR	7.372/125.4	BUD	240703	2.0009.303	BUD
304	17C2D2056D0545B3A88ECE80B8A8B914	240703	2.0009.AR	7.375/126.1	BUD	240703	2.0009.304	BUD
305	06B7C4502B5E4F8C954D8513493E544B	240703	2.0009.AR	7.381/226.1	BUD	240703	2.0009.305	BUD
306	EA772BEB9F634AF98110A6C473A7EA8F	240703	2.0009.AR	7.381/226.2	BUD	240703	2.0009.306	BUD
307	C4D03B0192644862ACBE57A827B6FE1F	240703	2.0009.AR	7.381/226.3	BUD	240703	2.0009.307	BUD
308	4488074FCAF84CE490F7C1737EA4ED23	240703	2.0009.AR	7.381/226.4	BUD	240703	2.0009.308	BUD
309	E3BFBCBCBE1341D1B67768C23044A74C	240703	2.0009.AR	7.383/26.1	BUD	240703	2.0009.309	BUD
310	94F67FF7585C46149AC069BB94DFD7AB	240703	2.0009.AR	7.383/26.2	BUD	240703	2.0009.310	BUD
311	AEA60D068DE04854A49315DD6BFFDE41	240703	2.0009.AR	7.397/26.1	BUD	240703	2.0009.311	BUD
312	4A83A8FF2801427DAE57A4DC3885D82B	240703	2.0009.AR	7.398/26.1	BUD	240703	2.0009.312	BUD
313	80E3029F3F69428B88B7BC76875DA6E3	240703	2.0009.AR	7.398/26.2	BUD	240703	2.0009.313	BUD
314	D6DBC3E25D004BCAAB83A674DA429F0B	240703	2.0009.AR	7.398/26.3	BUD	240703	2.0009.314	BUD
315	80FAA9686EED4ABE90A472CF635B9D7E	240703	2.0009.AR	7.398/26.4	BUD	240703	2.0009.315	BUD
316	20BAE9D4166D4449526E1AD246083DA	240703	2.0009.AR	7.402/26.1	BUD	240703	2.0009.316	BUD
317	8F835615BC73428AA3C35B877C7B5CB5	240703	2.0009.AR	7.402/26.2	BUD	240703	2.0009.317	BUD
318	4602C6478995432CAB3F7CFA207E9772	240703	2.0009.AR	7.402/26.3	BUD	240703	2.0009.318	BUD
319	6164356852494F78A49279D0E38A883E	240703	2.0009.AR	7.405/163.1	BUD	240703	2.0009.319	BUD
320	D47F4B23387E4431947B399080498EA3	240703	2.0009.AR	7.405/163.2	BUD	240703	2.0009.320	BUD
321	839B6720659643D48B042A5FB888A4CD	240703	2.0009.AR	7.405/163.3	BUD	240703	2.0009.321	BUD

322	D5FBBE82EFC48A493356B216BA4F5F9	240703	2.0009.AR	7.405/163.4	BUD	240703	2.0009.322	BUD
323	FC064DF9194C472CBE01394ED3AF28E4	240703	2.0009.AR	7.409/26.1	BUD	240703	2.0009.323	BUD
324	0FD87CB57B824982BAF9B2E5F8F0BC7C	240703	2.0009.AR	7.409/26.2	BUD	240703	2.0009.324	BUD
325	90326109F8674B379C57FE0D6A6CC348	240703	2.0009.AR	7.411/26.1	BUD	240703	2.0009.325	BUD
326	265AC9F954344CCC9D30A799E8F05B66	240703	2.0009.AR	7.411/26.2	BUD	240703	2.0009.326	BUD
327	33FD5681EE334720AAA0B4643A9C4D7D	240703	2.0009.AR	7.411/26.3	BUD	240703	2.0009.327	BUD
328	D66D84F830C245E393D8BC20AFF1062D	240703	2.0009.AR	7.412/26.1	BUD	240703	2.0009.328	BUD
329	CD0CD28D45A34D99B6CBB7F81C196BA6	240703	2.0009.AR	7.412/26.2	BUD	240703	2.0009.329	BUD
330	590DAC3F776040A194618761F949A3D3	240703	2.0009.AR	7.412/26.3	BUD	240703	2.0009.330	BUD
331	C7B04682F4BA45AD96AFFC163BEBB52A	240703	2.0009.AR	7.412/26.4	BUD	240703	2.0009.331	BUD
332	79EB416468F748CDB1A101F375C52174	240703	2.0009.AR	7.412/26.5	BUD	240703	2.0009.332	BUD
333	FE33FB49ECB047EC926F3F72152F9ACE	240703	2.0009.AR	7.423/14.1	BUD	240703	2.0009.333	BUD
334	CB40AF279E5A467B93E6610C4BF32B94	240703	2.0009.AR	7.424/14.1	BUD	240703	2.0009.334	BUD
335	F398344B5B934CA3BC584735E80EDC8D	240703	2.0009.AR	7.424/14.2	BUD	240703	2.0009.335	BUD
336	D1E9E346AD0E40B89A4C68F0C2B8B585	240703	2.0009.AR	7.447/183.1	BUD	240703	2.0009.336	BUD
337	ACFE9955832746C683D4615363DF96DF	240703	2.0009.AR	7.447/183.2	BUD	240703	2.0009.337	BUD
338	8013021D7E884DC7BCBBD50C7525A1D1	240703	2.0009.AR	7.515/47.1	BUD	240703	2.0009.338	BUD
339	96B93FD27DF74E2596E0D178DEC699AE	240703	2.0009.AR	7.515/47.2	BUD	240703	2.0009.339	BUD
340	D95A245CA0C94C828BEA8B1C6D73261A	240703	2.0009.AR	7.517/134.1	BUD	240703	2.0009.340	BUD
341	CB7D0CFBB47B43A3A046EE01E1DECF5C	240703	2.0009.AR	7.517/134.2	BUD	240703	2.0009.341	BUD
342	EF431E9C34734889D8EEE9888032509	240703	2.0009.AR	7.517/134.3	BUD	240703	2.0009.342	BUD
343	AE15BA00C8D64EA5A0B746C00324FDC7	240703	2.0009.AR	7.518/134.1	BUD	240703	2.0009.343	BUD
344	9525EB43CD284CAA9C7615C0D2DEB14C	240703	2.0009.AR	7.521/98.1	BUD	240703	2.0009.344	BUD
345	7A6210910EB34940B98FBEB9DE50165C	240703	2.0009.AR	7.523/98.1	BUD	240703	2.0009.345	BUD
346	C784181617244FD9A839951E9EDB32C5	240703	2.0009.AR	7.524/98.1	BUD	240703	2.0009.346	BUD
347	964E4C3FBD7B48B2AB1FFC24193D390E	240703	2.0009.AR	7.524/98.2	BUD	240703	2.0009.347	BUD
348	BDAE6F61FF4D4886851D10B1A4BFCDC1	240703	2.0009.AR	7.527/98.1	BUD	240703	2.0009.348	BUD
349	0C8B194A180D42CC94F2971CFA82A496	240703	2.0009.AR	7.534/98.1	BUD	240703	2.0009.349	BUD
350	7488805EF1874586BA122570D79BFC00	240703	2.0009.AR	7.536/98.1	BUD	240703	2.0009.350	BUD
351	E2AF1E168760471FB32442B0657C171D	240703	2.0009.AR	7.537/98.1	BUD	240703	2.0009.351	BUD
352	8D570922D1F94460B07CBBAD8C396348	240703	2.0009.AR	7.537/98.2	BUD	240703	2.0009.352	BUD
353	F13C77BB4C0444209AF7EBA295C77A42	240703	2.0009.AR	7.539/98.1	BUD	240703	2.0009.353	BUD
354	B4CCE884020C45B88125DA9C666556AD	240703	2.0009.AR	7.541/98.1	BUD	240703	2.0009.354	BUD
355	4EFEF523B7544CB89D8778F7E1646AC0	240703	2.0009.AR	7.541/98.2	BUD	240703	2.0009.355	BUD
356	B8519279E9A94467BBD0EDE96BC7E7C5	240703	2.0009.AR	7.541/98.3	BUD	240703	2.0009.356	BUD
357	EC0F550EA3E44C55AF7EE5F047AB27D0	240703	2.0009.AR	7.545/40.1	BUD	240703	2.0009.357	BUD
358	1DCEDC2FF027466D95F8FAD0196446D8	240703	2.0009.AR	7.549/98.1	BUD	240703	2.0009.358	BUD
359	CDB00CE875BD44E99453F7C04368FC0D	240703	2.0009.AR	7.550/179.1	BUD	240703	2.0009.359	BUD
360	37A3F24735EB4E4EA8573F62B589B8C1	240703	2.0009.AR	7.550/179.2	BUD	240703	2.0009.360	BUD
361	7850EFF8BAD149168BB40ABB15B9EEC1	240703	2.0009.AR	7.550/179.3	BUD	240703	2.0009.361	BUD
362	7745192C59554427815D2C6F601FBA3D	240703	2.0009.AR	7.554/132.1	BUD	240703	2.0009.362	BUD
363	B62B13E8DEEC4605AFEADD9CD8BC546D	240703	2.0009.AR	7.554/132.2	BUD	240703	2.0009.363	BUD
364	F2315716083A44B99422884270E59A34	240703	2.0009.AR	7.554/132.3	BUD	240703	2.0009.364	BUD
365	21CB743103404B3A926C002923E1C71A	240703	2.0009.AR	7.554/132.4	BUD	240703	2.0009.365	BUD
366	05F32C7E7A0A4F3C9CF26A314BF0E488	240703	2.0009.AR	7.592/172.1	BUD	240703	2.0009.366	BUD
367	49D69C5C9A6E4FAD9B6AFDF3123066B6	240703	2.0009.AR	8.22.1	BUD	240703	2.0009.367	BUD
368	640B9332C523456F90571C197F01F936	240703	2.0009.AR	8.22.2	BUD	240703	2.0009.368	BUD
369	7A368423E45A4999909AC7287E59EE12	240703	2.0009.AR	8.23.1	BUD	240703	2.0009.369	BUD
370	621E8B7BC84E4944923BE9C3FC01F095	240703	2.0009.AR	8.23.2	BUD	240703	2.0009.370	BUD
371	B7D9DBB424514431A04E52341B428A6B	240703	2.0009.AR	8.23.3	BUD	240703	2.0009.371	BUD
372	786A229B2AC2457F9E4137B93C86A62A	240703	2.0009.AR	8.26.1	BUD	240703	2.0009.372	BUD
373	5B38849F6E264B94BE8BF57484A05866	240703	2.0009.AR	8.26.2	BUD	240703	2.0009.373	BUD
374	C23461B1712D4CA09DDE9C1D2459488E	240703	2.0009.AR	8.31.1	BUD	240703	2.0009.374	BUD
375	F9A90247218E4A8ABB3DE3CB91BEF23E	240703	2.0009.AR	8.31.2	BUD	240703	2.0009.375	BUD
376	C0037866004E4F6C85E917EE76ABA704	240703	2.0009.AR	8.32.1	BUD	240703	2.0009.376	BUD
377	669CEF34B83E40E0A0FEAFA9642985C1	240703	2.0009.AR	8.32.2	BUD	240703	2.0009.377	BUD
378	FEB35678BE5E41AE847BF0E1DEEFE1BC	240703	2.0009.AR	8.54.1	BUD	240703	2.0009.378	BUD
379	C3EB29960CAD4ADC943E4C1F9A43E35B	240703	2.0009.AR	8.56.1	BUD	240703	2.0009.379	BUD
380	3673E711B26642979179B88D96431C73	240703	2.0009.AR	8.56.2	BUD	240703	2.0009.380	BUD
381	9D37680CF6234874B0B64D143D7A1746	240703	2.0009.AR	8.56.3	BUD	240703	2.0009.381	BUD
382	764E4C06CEAC420B98E0AC6CD48EF195	240703	2.0009.AR	8.57.1	BUD	240703	2.0009.382	BUD
383	C70816FE89304F48B08BD9B2D3CF16C1	240703	2.0009.AR	8.57.2	BUD	240703	2.0009.383	BUD
384	DA1E57AAA9E546DB90FEF86399D67485	240703	2.0009.AR	8.58.1	BUD	240703	2.0009.384	BUD
385	0DDC5E9DAF274BD38D664D13DBDA8F30	240703	2.0009.AR	8.58.2	BUD	240703	2.0009.385	BUD
386	0B65FB0EA43E47D19FB1D9DBE1EAD8CC	240703	2.0009.AR	8.58.3	BUD	240703	2.0009.386	BUD
387	84B86BC158384F039AF31C9CDFD7BCB9	240703	2.0009.AR	8.58.4	BUD	240703	2.0009.387	BUD

388	AD920E77C22E4D2CB6792C08BFE5ADEE	240703	2.0009.AR	8.71.1	BUD	240703	2.0009.388	BUD
389	FC137284DC844AD3B903467E860E90D0	240703	2.0009.AR	8.71.2	BUD	240703	2.0009.389	BUD
390	95C759F359B046779DD0B59BEC6A06E3	240703	2.0009.AR	8.71.3	BUD	240703	2.0009.390	BUD
391	A64EFD3EFE75469199AE4A489A7643F3	240703	2.0009.AR	8.72.1	BUD	240703	2.0009.391	BUD
392	A888C4A7C5834FC9AEF34012B441A556	240703	2.0009.AR	8.72.2	BUD	240703	2.0009.392	BUD
393	B4054F98D1354930950E9DCFFD3BD748	240703	2.0009.AR	8.72.3	BUD	240703	2.0009.393	BUD
394	0D83C35BDB54469A94E2C75BF23AA4A0	240703	2.0009.AR	8.72.4	BUD	240703	2.0009.394	BUD
395	A9ED23C342E3415898246D45098B4C95	240703	2.0009.AR	8.73.1	BUD	240703	2.0009.395	BUD
396	DD8DFA66879F4F2A8A4DE325C5B8667B	240703	2.0009.AR	8.73.2	BUD	240703	2.0009.396	BUD
397	5369DC051F724C47B64CAB3EA2836525	240703	2.0009.AR	8.73.3	BUD	240703	2.0009.397	BUD
398	C03B8C84C65E491A99BBD4EAD45D92F7	240703	2.0009.AR	8.75.1	BUD	240703	2.0009.398	BUD
399	410319C7AF3E40C59F286E9F312C37A9	240703	2.0009.AR	8.76.1	BUD	240703	2.0009.399	BUD
400	D1A1B62425BA497A8ABFA7C0577464B8	240703	2.0009.AR	8.76.2	BUD	240703	2.0009.400	BUD
401	A05FBE0499E748F492541F5569E47B42	240703	2.0009.AR	8.78.1	BUD	240703	2.0009.401	BUD
402	82B445AE904742E78896BC2CA1A17901	240703	2.0009.AR	8.78.2	BUD	240703	2.0009.402	BUD
403	74984910CF6147C68A3903D757CB00BB	240703	2.0009.AR	8.84.1	BUD	240703	2.0009.403	BUD
404	60BDC74C80AF4339AF8D04C6FD37F33C	240703	2.0009.AR	8.85.1	BUD	240703	2.0009.404	BUD
405	2C4079F22C82478197B073BF45AC1654	240703	2.0009.AR	8.116.1	BUD	240703	2.0009.405	BUD
406	9502E11447B545C9BA5F03CF17E571FB	240703	2.0009.AR	8.120.1	BUD	240703	2.0009.406	BUD
407	C27C251A41DA4ED7B7C132A53A1935F5	240703	2.0009.AR	8.121.1	BUD	240703	2.0009.407	BUD
408	37F122C931D14491AB8D501CE47DDACF	240703	2.0009.AR	8.121.2	BUD	240703	2.0009.408	BUD
409	3080D026A6AD499EB5CECE636225820B	240703	2.0009.AR	8.121.3	BUD	240703	2.0009.409	BUD
410	B4E81E16EA2F479B9E080C63B5F1226D	240703	2.0009.AR	8.122.1	BUD	240703	2.0009.410	BUD
411	9B0EBA7869F6471A900F056639DAD930	240703	2.0009.AR	8.122.2	BUD	240703	2.0009.411	BUD
412	22A1771F566245E8B9EE728CB463AE17	240703	2.0009.AR	8.124.1	BUD	240703	2.0009.412	BUD
413	541F47DFFFF54F13AE49D2AB47681623	240703	2.0009.AR	8.124.2	BUD	240703	2.0009.413	BUD
414	65D04879791E4AA19F93B14FC0F2AA9A	240703	2.0009.AR	8.127.1	BUD	240703	2.0009.414	BUD
415	15F413B58C20494B92042D0CDDD943A7	240703	2.0009.AR	8.129.1	BUD	240703	2.0009.415	BUD
416	7DFF75D5CFCD4B9BA89E59B9FB45798	240703	2.0009.AR	8.130.1	BUD	240703	2.0009.416	BUD
417	07A020D3C4C94FD0B0888CDEAC77635D	240703	2.0009.AR	8.130.2	BUD	240703	2.0009.417	BUD
418	4F9B583EFF104665BD927830CF551759	240703	2.0009.AR	8.131.1	BUD	240703	2.0009.418	BUD
419	A085FA78A3D143B0B2425AD59A71052D	240703	2.0009.AR	8.137.1	BUD	240703	2.0009.419	BUD
420	8265AC2303204DEA9E81958D0C218710	240703	2.0009.AR	8.137.2	BUD	240703	2.0009.420	BUD
421	44117E6190034BC0AD329DD12327F068	240703	2.0009.AR	8.137.3	BUD	240703	2.0009.421	BUD
422	B1071D20E94F4500BC473B6FA1BC975C	240703	2.0009.AR	8.138.1	BUD	240703	2.0009.422	BUD
423	D04079037985420BA47709B7DEF3BE5F	240703	2.0009.AR	8.138.2	BUD	240703	2.0009.423	BUD
424	5E0AB2DEC7B5487BBE546D9645C3486B	240703	2.0009.AR	8.138.3	BUD	240703	2.0009.424	BUD
425	B568A904503B477FAEB954490849FF96	240703	2.0009.AR	8.138.4	BUD	240703	2.0009.425	BUD
426	5FFB804532FC409A858EC37C13C126CA	240703	2.0009.AR	8.139.1	BUD	240703	2.0009.426	BUD
427	5AB456AEC39C40A8A0AF59F6C057A196	240703	2.0009.AR	8.139.2	BUD	240703	2.0009.427	BUD
428	CCB42D3526B34AAA8D9AD28D119A7395	240703	2.0009.AR	8.139.3	BUD	240703	2.0009.428	BUD
429	9E05542DFDF94CCCA99D5A5AA1F412A7	240703	2.0009.AR	8.139.4	BUD	240703	2.0009.429	BUD
430	1813D4D9AB664920A19BD540C42294C7	240703	2.0009.AR	8.140.1	BUD	240703	2.0009.430	BUD
431	C05227E112DE409CA541801B5503E080	240703	2.0009.AR	8.140.2	BUD	240703	2.0009.431	BUD
432	3D321BF15D984E3B979D2B4FF9DEEA77	240703	2.0009.AR	8.150.1	BUD	240703	2.0009.432	BUD
433	7BCD759A78D64E4C95E7D51CF1FCD9BC	240703	2.0009.AR	8.150.2	BUD	240703	2.0009.433	BUD
434	5DD7A1C4988545648593C3687E597ECB	240703	2.0009.AR	8.150.3	BUD	240703	2.0009.434	BUD
435	C0C347D1BBE34D50A8BCFF92B5EF431A	240703	2.0009.AR	8.150.4	BUD	240703	2.0009.435	BUD
436	AD17442DCD6A4A12A6F2F035B06AE2FD	240703	2.0009.AR	8.154.1	BUD	240703	2.0009.436	BUD
437	394CD6BDC7D74C0CB902F81FBA424289	240703	2.0009.AR	8.154.2	BUD	240703	2.0009.437	BUD
438	6C3AB93D3B0746509C0E03B875F35A09	240703	2.0009.AR	8.163.1	BUD	240703	2.0009.438	BUD
439	B214E44CC0624F97AEC70C4B6CACB557	240703	2.0009.AR	8.163.2	BUD	240703	2.0009.439	BUD
440	6C02D1BCE13D46619303E47F10D7D4CC	240703	2.0009.AR	8.165.1	BUD	240703	2.0009.440	BUD
441	3DB669D069A5446C84F0C9A5F60DD1AB	240703	2.0009.AR	8.165.2	BUD	240703	2.0009.441	BUD
442	FBBA748097514C19897EB4A8E00C37FC	240703	2.0009.AR	8.169.1	BUD	240703	2.0009.442	BUD
443	5ABB48F77862400EA5A1E8853793B8B6	240703	2.0009.AR	8.170.1	BUD	240703	2.0009.443	BUD
444	BEB3732D5349438DB9E63D97AD196667	240703	2.0009.AR	8.190.1	BUD	240703	2.0009.444	BUD
445	0D90FCBB43E14D958EF013032C6D8DEE	240703	2.0009.AR	8.195.1	BUD	240703	2.0009.445	BUD
446	7662B57F40664D6893E87BAD73A6F5CF	240703	2.0009.AR	8.195.2	BUD	240703	2.0009.446	BUD
447	4A23A53E5F694CF391D1AC764F697E16	240703	2.0009.AR	8.240/135.1	BUD	240703	2.0009.447	BUD
448	AFDC87B2BC7D45DA97CAF0F99890C07C	240703	2.0009.AR	8.240/135.2	BUD	240703	2.0009.448	BUD
449	B89E843FFCB84970ABCDD19A6D9638108	240703	2.0009.AR	8.253/145.1	BUD	240703	2.0009.449	BUD
450	2209AF46E4A64E86BDED4E17FB50262B	240703	2.0009.AR	8.253/145.2	BUD	240703	2.0009.450	BUD
451	6DE2347850CA49A9A87694CD95F9B23F	240703	2.0009.AR	8.253/145.3	BUD	240703	2.0009.451	BUD
452	59AD47DFDACB4391955040E1964DD8F9	240703	2.0009.AR	8.253/145.4	BUD	240703	2.0009.452	BUD
453	E5F999A7F4F74B86A745FD7A0C79B762	240703	2.0009.AR	8.263/4.1	BUD	240703	2.0009.453	BUD

454	67671073A1634F2490D4D4B494710753	240703	2.0009.AR	8.284/115.1	BUD	240703	2.0009.454	BUD
455	1A6C222BDDF14B64A0A5F56E338B6364	240703	2.0009.AR	8.285/117.1	BUD	240703	2.0009.455	BUD
456	9249CCD0CCDE4319AC4805A2035DE393	240703	2.0009.AR	8.285/117.2	BUD	240703	2.0009.456	BUD
457	5CFF4B3FE8E34F719600FB124A2E70FF	240703	2.0009.AR	8.285/117.3	BUD	240703	2.0009.457	BUD
458	02D16D149EE5444DB5071F9B2A4739B7	240703	2.0009.AR	8.285/117.4	BUD	240703	2.0009.458	BUD
459	9C8DF1659B864257900E41C7F536A42E	240703	2.0009.AR	8.293/136.1	BUD	240703	2.0009.459	BUD
460	ADDE09ECBC8F4E6884DFA99C1B6D96A1	240703	2.0009.AR	8.293/136.2	BUD	240703	2.0009.460	BUD
461	ECA4A52D662D4917B42F460DFE934359	240703	2.0009.AR	8.295/136.1	BUD	240703	2.0009.461	BUD
462	9733D7C6807D448486CD79F16891D728	240703	2.0009.AR	8.295/136.2	BUD	240703	2.0009.462	BUD
463	756F2B26D7CE42328F86ADEC80BD015F	240703	2.0009.AR	8.295/136.3	BUD	240703	2.0009.463	BUD
464	98778EEA527E4FD3A325047B37D01908	240703	2.0009.AR	8.295/136.4	BUD	240703	2.0009.464	BUD
465	B9E25E8EB47344F68FFC17FC0E649B2D	240703	2.0009.AR	8.297/136.1	BUD	240703	2.0009.465	BUD
466	F1965CCA08784B13BF146367F427C584	240703	2.0009.AR	8.297/136.2	BUD	240703	2.0009.466	BUD
467	FA9BE48568A14133B375987B71307561	240703	2.0009.AR	8.297/136.3	BUD	240703	2.0009.467	BUD
468	FA43B7E6C20D4B4097A9D096AB16C806	240703	2.0009.AR	8.300/153.1	BUD	240703	2.0009.468	BUD
469	64C962E6842542039452A550E82422C8	240703	2.0009.AR	8.300/153.2	BUD	240703	2.0009.469	BUD
470	67385541C152484984391E632F94A86E	240703	2.0009.AR	8.308/158.1	BUD	240703	2.0009.470	BUD
471	0FB9C066A6D345F79AAABABCE1CE6C26	240703	2.0009.AR	8.342/6.1	BUD	240703	2.0009.471	BUD
472	CD2ADCEB534F44CA8F4620A55ECF1EB5	240703	2.0009.AR	8.345/5.1	BUD	240703	2.0009.472	BUD
473	457BB034C15548048EBF945C604C4CAC	240703	2.0009.AR	8.345/5.2	BUD	240703	2.0009.473	BUD
474	E7FD977F9D5C449BB886F6AB5CC961F7	240703	2.0009.AR	8.345/5.3	BUD	240703	2.0009.474	BUD
475	17E45949F8F141D0B9DCE6B410AAC496	240703	2.0009.AR	8.345/5.4	BUD	240703	2.0009.475	BUD
476	99016A79455B449882F5F782843DBC15	240703	2.0009.AR	8.350/201.1	BUD	240703	2.0009.476	BUD
477	FA5D87B4D355475F8A9BF44838235ABE	240703	2.0009.AR	8.360/145.1	BUD	240703	2.0009.477	BUD
478	F1398BB03C824948A0FDB01C82E6DF74	240703	2.0009.AR	8.360/145.2	BUD	240703	2.0009.478	BUD
479	DF0B543E2C80486FBAD310E8A80F2D83	240703	2.0009.AR	8.362/160.1	BUD	240703	2.0009.479	BUD
480	B4306B7108A44DC0A5DF1D4A5D429E54	240703	2.0009.AR	8.362/160.2	BUD	240703	2.0009.480	BUD
481	7830637356A24FD885F79BE8B910E5C0	240703	2.0009.AR	8.362/160.3	BUD	240703	2.0009.481	BUD
482	5CC2C45A4E6C4453A02257CAA52312D5	240703	2.0009.AR	8.364/160.1	BUD	240703	2.0009.482	BUD
483	F882A2388A854A8389C67A2B27FA1104	240703	2.0009.AR	8.364/160.2	BUD	240703	2.0009.483	BUD
484	29C05E9A23464A9B8A8A169966CD8237	240703	2.0009.AR	8.364/160.3	BUD	240703	2.0009.484	BUD
485	3436320A8B1A4DD3A00A22EB3F8F83CF	240703	2.0009.AR	8.366/2.1	BUD	240703	2.0009.485	BUD
486	A5EA8CF48A584F148CA4E16AD7D53494	240703	2.0009.AR	8.366/2.2	BUD	240703	2.0009.486	BUD
487	5EBB542CF7954AEF81A30F4BA2033ADE	240703	2.0009.AR	8.366/2.3	BUD	240703	2.0009.487	BUD
488	79E2191A7C574F06ABA58701A98E007F	240703	2.0009.AR	8.366/2.4	BUD	240703	2.0009.488	BUD
489	794822F384F7442286CBCC3C1ACDB3E9	240703	2.0009.AR	8.368/65.1	BUD	240703	2.0009.489	BUD
490	2C235E908B8F4938B21FFD2A13A278AD	240703	2.0009.AR	8.368/65.2	BUD	240703	2.0009.490	BUD
491	C05BD053B0574AD194DE05950FC75C11	240703	2.0009.AR	8.368/65.3	BUD	240703	2.0009.491	BUD
492	A9DAC60907FC4E52B4103F107EC2FC5A	240703	2.0009.AR	8.369/67.1	BUD	240703	2.0009.492	BUD
493	225EEFCDD171441068C15F5E2A1758D69	240703	2.0009.AR	8.369/67.2	BUD	240703	2.0009.493	BUD
494	642CCB0AB4D04546BF242836E8C0262A	240703	2.0009.AR	8.369/67.3	BUD	240703	2.0009.494	BUD
495	E434185674AD417B82DBAB70F7BA9447	240703	2.0009.AR	8.369/67.4	BUD	240703	2.0009.495	BUD
496	0EC424EF2896429AAC015FBC32D8F2D1	240703	2.0009.AR	8.370/67.1	BUD	240703	2.0009.496	BUD
497	37B589920D4F4D1880D1C1EC798F966A	240703	2.0009.AR	8.371/67.1	BUD	240703	2.0009.497	BUD
498	9F18BF4184E54CC0B7AB96DF5D96479E	240703	2.0009.AR	8.374/155.1	BUD	240703	2.0009.498	BUD
499	9D8E78DD1A8E43369E6F7E0F022A24F0	240703	2.0009.AR	8.374/155.2	BUD	240703	2.0009.499	BUD
500	CE91447129A14D42A732012C96F7E9D4	240703	2.0009.AR	8.374/155.3	BUD	240703	2.0009.500	BUD
501	0C08EEB466C749E4A6C2A1E2D84E2F49	240703	2.0009.AR	8.374/155.4	BUD	240703	2.0009.501	BUD
502	1718C94481EC47769D1F116A038BFF1A	240703	2.0009.AR	8.376/168.1	BUD	240703	2.0009.502	BUD
503	BAD1B6BFF030477690C85E5F36C2F90C	240703	2.0009.AR	8.376/168.2	BUD	240703	2.0009.503	BUD
504	2A367A9547E842FB92B239B55CE21AFE	240703	2.0009.AR	8.377/168.1	BUD	240703	2.0009.504	BUD
505	74396A1F6A4C43DDAEBB550AF401FD9A	240703	2.0009.AR	8.378/19.1	BUD	240703	2.0009.505	BUD
506	23B9CF881CCF4B9CABBAF69B5DC91345	240703	2.0009.AR	8.378/19.2	BUD	240703	2.0009.506	BUD
507	6268D57B95464D37B7EBE452C02D5B9C	240703	2.0009.AR	8.378/19.3	BUD	240703	2.0009.507	BUD
508	EF6F040EA2FD4DA187FEE70237F462C1	240703	2.0009.AR	8.378/19.4	BUD	240703	2.0009.508	BUD
509	78C2B913AF6C453A841942B004829639	240703	2.0009.AR	8.384/136.1	BUD	240703	2.0009.509	BUD
510	E0E2341707C046C088D481728C2F2E0F	240703	2.0009.AR	8.384/136.2	BUD	240703	2.0009.510	BUD
511	87A983B9C25A4EA8AB6781331A017AE6	240703	2.0009.AR	8.386/191.1	BUD	240703	2.0009.511	BUD
512	593D839B75714E86ACFD66161B907374	240703	2.0009.AR	8.386/191.2	BUD	240703	2.0009.512	BUD
513	72F179A5294A4F5FADA0C8A7C62C890F	240703	2.0009.AR	8.386/191.3	BUD	240703	2.0009.513	BUD
514	553DF28DA5A5041AFB1316210C8413570	240703	2.0009.AR	8.387/191.1	BUD	240703	2.0009.514	BUD
515	45340341AF7740E295FD8BD2CAB52D5E	240703	2.0009.AR	8.387/191.2	BUD	240703	2.0009.515	BUD
516	C7B2F5785B7D47C7820198572574C6BE	240703	2.0009.AR	8.390/148.1	BUD	240703	2.0009.516	BUD
517	B7433E8328CE4302AAE3857B5F51A841	240703	2.0009.AR	8.390/148.2	BUD	240703	2.0009.517	BUD
518	59B32570F3E6405DB99A12A2C28B98AF	240703	2.0009.AR	8.390/148.3	BUD	240703	2.0009.518	BUD
519	BA8876696E2B4A45A26C7E881318F6CD	240703	2.0009.AR	8.390/148.4	BUD	240703	2.0009.519	BUD

520	F2460DC8761D4175BEC8BECB859C40AA	240703	2.0009.AR	8.390/148.5	BUD	240703	2.0009.520	BUD
521	EB8537056684455492096B17547828DA	240703	2.0009.AR	8.392/148.1	BUD	240703	2.0009.521	BUD
522	87E4A1AF08404CD09141FFBAA79272C8	240703	2.0009.AR	8.392/148.2	BUD	240703	2.0009.522	BUD
523	5FD36E22E2394B2EBFF3B116E6E226BF	240703	2.0009.AR	8.392/148.3	BUD	240703	2.0009.523	BUD
524	AE1EA9B3E83749B9856BE16EA00506D9	240703	2.0009.AR	8.393/199.1	BUD	240703	2.0009.524	BUD
525	0C632F62B7F449F9BEA763CC0A9EC7CD	240703	2.0009.AR	8.393/199.2	BUD	240703	2.0009.525	BUD
526	EBEBB8572C04402EA89D87D2D6D49402	240703	2.0009.AR	8.393/199.3	BUD	240703	2.0009.526	BUD
527	77A8CE1F027142C591D154BDBBB7844F	240703	2.0009.AR	8.394/199.1	BUD	240703	2.0009.527	BUD
528	ED2A21E29987452E9AD511ECDA288A39	240703	2.0009.AR	8.394/199.2	BUD	240703	2.0009.528	BUD
529	6C0F120732CC4EAF90EEDBA711D2488B	240703	2.0009.AR	8.395/199.1	BUD	240703	2.0009.529	BUD
530	9CCA84158FA04E2A92924C682B2AE7F5	240703	2.0009.AR	8.397/199.1	BUD	240703	2.0009.530	BUD
531	113A00479576425D9E97122392835F76	240703	2.0009.AR	8.397/199.2	BUD	240703	2.0009.531	BUD
532	A1E4F545F35C49A5892240B97E3AC54B	240703	2.0009.AR	8.399/199.1	BUD	240703	2.0009.532	BUD
533	66AFC1A2B0D049C39FDD3DE250E95233	240703	2.0009.AR	8.399/199.2	BUD	240703	2.0009.533	BUD
534	D647D4E592F84111A0555650445243B3	240703	2.0009.AR	8.399/199.3	BUD	240703	2.0009.534	BUD
535	9E18405BB4B44B40887AA4ED30C0C50C	240703	2.0009.AR	8.400/6.1	BUD	240703	2.0009.535	BUD
536	4A16A3B33B244F2C8FFC88C477585179	240703	2.0009.AR	8.400/6.2	BUD	240703	2.0009.536	BUD
537	E257BA2792124AB0842E638804260FB7	240703	2.0009.AR	8.400/6.3	BUD	240703	2.0009.537	BUD
538	DE693D56EABC497B881DCF82A64CF58A	240703	2.0009.AR	8.400/6.4	BUD	240703	2.0009.538	BUD
539	CF99022F1D3E44FA8831C7DC2C67AA06	240703	2.0009.AR	8.402/189.1	BUD	240703	2.0009.539	BUD
540	44FB302A5D6243DA87C5E740E118E8A0	240703	2.0009.AR	8.406/189.1	BUD	240703	2.0009.540	BUD
541	BF86F65F5C6B4009B31C24C4122ABAAA	240703	2.0009.AR	8.406/189.2	BUD	240703	2.0009.541	BUD
542	E4DD87D21DC44867B1AA4C80F11810B8	240703	2.0009.AR	8.409/189.1	BUD	240703	2.0009.542	BUD
543	6065214B7A5948C283A4B36849308CF7	240703	2.0009.AR	8.411/189.1	BUD	240703	2.0009.543	BUD
544	587BDE83967D4DE7AB491691F249B669	240703	2.0009.AR	8.411/189.2	BUD	240703	2.0009.544	BUD
545	B95AA6E856044FCE8755E24C3470C0AB	240703	2.0009.AR	8.413/197.1	BUD	240703	2.0009.545	BUD
546	E86324AB784741ECABEF784B8A54059C	240703	2.0009.AR	8.413/197.2	BUD	240703	2.0009.546	BUD
547	5E67D6C1476E4FE6B35D4E4BD2D883CF	240703	2.0009.AR	8.413/197.3	BUD	240703	2.0009.547	BUD
548	5EF803CC40F44B90AC148BEF83D4208C	240703	2.0009.AR	8.414/197.1	BUD	240703	2.0009.548	BUD
549	E3D1F4988D674D618091284AA0E1503F	240703	2.0009.AR	8.415/4.1	BUD	240703	2.0009.549	BUD
550	F28CCB0F91594E29B6F1BFBD56675DE1	240703	2.0009.AR	8.415/4.2	BUD	240703	2.0009.550	BUD
551	8BC0FEAE3B6429180E836CC8D705E94	240703	2.0009.AR	8.416/4.1	BUD	240703	2.0009.551	BUD
552	18D806D923A843C39F566E30EC4B8E2C	240703	2.0009.AR	8.416/4.2	BUD	240703	2.0009.552	BUD
553	81A4FF4B0BCF4857B96DA23D39407F14	240703	2.0009.AR	8.417/79.1	BUD	240703	2.0009.553	BUD
554	7EA3508A007994D05BF58DE9640E2E8CF	240703	2.0009.AR	8.419/161.1	BUD	240703	2.0009.554	BUD
555	259B36912E5A4BA38B5F0DB473E5FBFE	240703	2.0009.AR	8.420/161.1	BUD	240703	2.0009.555	BUD
556	1AFA0359684E430EAF976D10259C044E	240703	2.0009.AR	8.420/161.2	BUD	240703	2.0009.556	BUD
557	8A2B34958CFA40549E92BD4495A17D744	240703	2.0009.AR	8.421/3.1	BUD	240703	2.0009.557	BUD
558	B2B7CAC12A544536BEB234C985C339A5	240703	2.0009.AR	8.421/3.2	BUD	240703	2.0009.558	BUD
559	A526C4CCCE2E495496C1FAAD04830336	240703	2.0009.AR	8.422/3.1	BUD	240703	2.0009.559	BUD
560	FCE71788645E46EA8874E1BAB836D224	240703	2.0009.AR	8.422/3.2	BUD	240703	2.0009.560	BUD
561	9C357B22E1764FB2898C2C5E9A8FCFB1	240703	2.0009.AR	8.422/3.3	BUD	240703	2.0009.561	BUD
562	70012D5ACEE1405797B43B383C7021CD	240703	2.0009.AR	8.422/3.4	BUD	240703	2.0009.562	BUD
563	E65B2C5939914559AC25E39DC7D4BD78	240703	2.0009.AR	8.422/3.5	BUD	240703	2.0009.563	BUD
564	8F0364B6ABAC4422BA50156FD38F48EA	240703	2.0009.AR	8.423/187.1	BUD	240703	2.0009.564	BUD
565	3BDA2AE1370646FA807169F7D9BB4BEB	240703	2.0009.AR	8.424/187.1	BUD	240703	2.0009.565	BUD
566	8A303BE02C11413CB98D7010E739EEF0	240703	2.0009.AR	8.424/187.2	BUD	240703	2.0009.566	BUD
567	F784F05AF6B84493900B679C646D841B	240703	2.0009.AR	8.425/187.1	BUD	240703	2.0009.567	BUD
568	6B4B336E9E5F4660A712E4F05E133533	240703	2.0009.AR	8.425/187.3	BUD	240703	2.0009.568	BUD
569	6FAFCF8D082744FF818230B9A7FD5E98	240703	2.0009.AR	8.426/187.1	BUD	240703	2.0009.569	BUD
570	D01EEE6AC69641919CB93E96CA15B55D	240703	2.0009.AR	8.427/187.1	BUD	240703	2.0009.570	BUD
571	4CC0054EFA3640DB8B69FF628A01F9FF	240703	2.0009.AR	8.427/187.2	BUD	240703	2.0009.571	BUD
572	9A9AA0B3D15E48FEABCC14525C81AB17	240703	2.0009.AR	8.429/61.1	BUD	240703	2.0009.572	BUD
573	60E3FDA5C09B4B9CABA901BA16C5C616	240703	2.0009.AR	8.429/61.2	BUD	240703	2.0009.573	BUD
574	05E07395AE9C41818D000A263B96E741	240703	2.0009.AR	8.429/61.3	BUD	240703	2.0009.574	BUD
575	CEEACC32E5D2436FB79ED370F026E5A6	240703	2.0009.AR	8.430/60.1	BUD	240703	2.0009.575	BUD
576	A0BBF5CC934440C895F2FCBBFE473BE0	240703	2.0009.AR	8.432/63.1	BUD	240703	2.0009.576	BUD
577	DE0E306E1F4F4B5881ECC5516B25B8F6	240703	2.0009.AR	8.432/63.2	BUD	240703	2.0009.577	BUD
578	6B86321EF55B4E7EBAA3C5057A5569A1	240703	2.0009.AR	8.432/63.3	BUD	240703	2.0009.578	BUD
579	34CFC55FDCCF469BBB6C7CEDDB089F77	240703	2.0009.AR	8.432/63.4	BUD	240703	2.0009.579	BUD
580	17D877CAA25F4D6BA253F9435E7C54AF	240703	2.0009.AR	8.434/1.1	BUD	240703	2.0009.580	BUD
581	F8B4306BA9064557AA9D0E4F3A1F6FEF	240703	2.0009.AR	8.434/1.2	BUD	240703	2.0009.581	BUD
582	430BB7BC3AB34FB0A4F29AE4641A5D7D	240703	2.0009.AR	8.441/1.1	BUD	240703	2.0009.582	BUD
583	81650F4BBF5540B8AD0BD1E68ED603C8	240703	2.0009.AR	8.446/1.1	BUD	240703	2.0009.583	BUD
584	C8956BD09A4A4ED3BB5CC5E050F8978F	240703	2.0009.AR	8.447/1.1	BUD	240703	2.0009.584	BUD
585	9D905BA66FE74E2B988E53F755376767	240703	2.0009.AR	8.447/1.2	BUD	240703	2.0009.585	BUD

586	76406D7A63F348F68366A573E3E16AB9	240703 2.0009.AR 8.448/1.1 BUD	240703 2.0009.586 BUD
587	875902558D4C4558BB07C07B38B4BF03	240703 2.0009.AR 8.448/1.2 BUD	240703 2.0009.587 BUD
588	27817ABDAB8C40AFA7F7CCB4CB57AD9A	240703 2.0009.AR 8.449/1.1 BUD	240703 2.0009.588 BUD
589	986B9898866C43599936F14A19AF0A2C	240703 2.0009.AR 8.450/1.1 BUD	240703 2.0009.589 BUD
590	9CDD36DBF4FA4D5EBAF51BA31A2B227E	240703 2.0009.AR 8.451/1.1 BUD	240703 2.0009.590 BUD
591	29FECB27C4284BB48A7AA2912EDFDE60	240703 2.0009.AR 8.454/145.1 BUD	240703 2.0009.591 BUD
592	C5E7FB98B4AE40ECA7D2ABC3AB5E8CD9	240703 2.0009.AR 8.454/145.2 BUD	240703 2.0009.592 BUD
593	FA232F0EF24846A2A26775685A199151	240703 2.0009.AR 8.455/145.1 BUD	240703 2.0009.593 BUD
594	71947C79D39F493FABDF1466A02DD6C3	240703 2.0009.AR 8.455/145.2 BUD	240703 2.0009.594 BUD
595	07A68B012B2F469DBBAA697B4AF0C960	240703 2.0009.AR 8.462/136.1 BUD	240703 2.0009.595 BUD
596	F95157D9EC6A4A6DBDB44148CCBEA960	240703 2.0009.AR 8.464/132.2 BUD	240703 2.0009.596 BUD
597	6D37EC34E6F84C3FB9705998767016D1	240703 2.0009.AR 8.465/132.1 BUD	240703 2.0009.597 BUD
598	4FC9F8C824404B8088CB358D41629057	240703 2.0009.AR 8.465/132.2 BUD	240703 2.0009.598 BUD
599	602DFE1971BB4E7BBDD08CFFC5B52379	240703 2.0009.AR 8.466/7.1 BUD	240703 2.0009.599 BUD
600	7C03216F00AD4614A6119A3947AC41AC	240703 2.0009.AR 8.466/7.2 BUD	240703 2.0009.600 BUD
601	DED6606868264F3BB1E6C3AD725F0D6F	240703 2.0009.AR 8.468/136.1 BUD	240703 2.0009.601 BUD
602	B42D247B57BD459B8948543883CF6723	240703 2.0009.AR 8.468/136.2 BUD	240703 2.0009.602 BUD
603	F3EAD04BDBEA4AFC8B3278804C1A1DC3	240703 2.0009.AR 8.469/136.1 BUD	240703 2.0009.603 BUD
604	8292E757C97444BC97540B138D311B03	240703 2.0009.AR 8.475/187.1 BUD	240703 2.0009.604 BUD
605	6520CCF7A7504FEBB2DFD5B29048C905	240703 2.0009.AR 8.479/187.1 BUD	240703 2.0009.605 BUD
606	C668C2F8C0C644939D2CAB5BB9434055	240703 2.0009.AR 8.479/187.2 BUD	240703 2.0009.606 BUD
607	86385EAEC591467FAC98C963222D65DC	240703 2.0009.AR 8.480/9.1 BUD	240703 2.0009.607 BUD
608	BF23C5FF36ED491D8443E9095535A9F3	240703 2.0009.AR 8.484/177.1 BUD	240703 2.0009.608 BUD
609	4B03723148FB4F9F98B60716E6252DF6	240703 2.0009.AR 8.487/177.1 BUD	240703 2.0009.609 BUD
610	FB4E772B48094CCE9EF27CCDDE596A50	240703 2.0009.AR 8.487/177.2 BUD	240703 2.0009.610 BUD
611	A3F466E846634421BB8EA4585DB5E31E	240703 2.0009.AR 8.487/177.3 BUD	240703 2.0009.611 BUD
612	AF06969DB0AA4F87B4E95DC509B9AEA2	240703 2.0009.AR 8.487/177.4 BUD	240703 2.0009.612 BUD
613	864D08B9BE744D549E9F753D91493322	240703 2.0009.AR 8.489/173.1 BUD	240703 2.0009.613 BUD
614	5B46FE16211E447B98F919978F344A5A	240703 2.0009.AR 8.489/173.2 BUD	240703 2.0009.614 BUD
615	289BF3E4AFB041A6A6D01C93BB970B92	240703 2.0009.AR 8.490/145.1 BUD	240703 2.0009.615 BUD
616	74CA12C5C9BF4788A8D38A14FC885B39	240703 2.0009.AR 8.490/145.2 BUD	240703 2.0009.616 BUD
617	0D95B8402EBA4226963EAC0276CFB03D	240703 2.0009.AR 8.490/145.3 BUD	240703 2.0009.617 BUD
618	4F6B5828FC714A78BFCBFC03D5728A3E	240703 2.0009.AR 8.491/145.1 BUD	240703 2.0009.618 BUD
619	A0C861C70FA846249984E5C5C8BCF76F	240703 2.0009.AR 8.491/145.2 BUD	240703 2.0009.619 BUD
620	DBF8ACE0EB884917991B14ADDB0C4607	240703 2.0009.AR 8.495/189.1 BUD	240703 2.0009.620 BUD
621	099FEE80B5E8472E94032C559B9EE362	240703 2.0009.AR 8.495/189.2 BUD	240703 2.0009.621 BUD
622	2476AA26D11D46A78D07FF1DCD12E0F1	240703 2.0009.AR 8.495/189.3 BUD	240703 2.0009.622 BUD
623	A7BF3BB8DBF744158D8A83ACD1D94E6E	240703 2.0009.AR 8.495/189.4 BUD	240703 2.0009.623 BUD
624	08F619A2121B4B6BA8059C53D86F88F0	240703 2.0009.AR 8.495/189.5 BUD	240703 2.0009.624 BUD
625	01139921AB864E04B7B77F5E610D4B07	240703 2.0009.AR 8.496/8.1 BUD	240703 2.0009.625 BUD
626	B67ECEDC4F3D46FDA67E761EA4D227CA	240703 2.0009.AR 8.497/8.1 BUD	240703 2.0009.626 BUD
627	F4DB29C04BE6472EA334F43D351045C7	240703 2.0009.AR 8.499/199.1 BUD	240703 2.0009.627 BUD
628	5E7D16379A744F7EAC87F1DCC1620F4F	240703 2.0009.AR 8.499/199.2 BUD	240703 2.0009.628 BUD
629	8998507D8AA14C7486280F21E6709357	240703 2.0009.AR 8.499/199.3 BUD	240703 2.0009.629 BUD
630	A53ECAE7F33D4192892E9B71480C4643	240703 2.0009.AR 8.507/191.1 BUD	240703 2.0009.630 BUD
631	DB34B1925FC746CC9DCFCFA77FDD04F8E	240703 2.0009.AR 8.513/184.1 BUD	240703 2.0009.631 BUD
632	E40A9F095BFD4B47B66963BACAA07E29	240703 2.0009.AR 8.515/155.1 BUD	240703 2.0009.632 BUD
633	1E654C60CF424531A6EF00F162837343	240703 2.0009.AR 8.527/36.2 BUD	240703 2.0009.633 BUD
634	D160E22069D54C1097D803C0F6403037	240703 2.0009.AR 8.531/3.1 BUD	240703 2.0009.634 BUD
635	4228D42239D343CA85DDE1ED48777A1F	240703 2.0009.AR 8.542/132.1 BUD	240703 2.0009.635 BUD
636	7FBE1CD9F1A742C89667D7738D27DD96	240703 2.0009.AR 9.23.1 BUD	240703 2.0009.636 BUD
637	865F0FA5FDC947E5AAF4EF75813B2F9F	240703 2.0009.AR 9.23.2 BUD	240703 2.0009.637 BUD
638	46144E9AC1704371B0155E8C138F25D4	240703 2.0009.AR 9.24.1 BUD	240703 2.0009.638 BUD
639	B923954B4CBD4DFCA4127C797DA38AD0	240703 2.0009.AR 9.24.2 BUD	240703 2.0009.639 BUD
640	40EBFE2B4E304CA185B6B51CCC3EAA32	240703 2.0009.AR 9.24.3 BUD	240703 2.0009.640 BUD
641	214D1F28855B46EAA69963751B94802C	240703 2.0009.AR 9.36.1 BUD	240703 2.0009.641 BUD
642	7FCA86EA3A81455B949DF741696F547	240703 2.0009.AR 9.36.2 BUD	240703 2.0009.642 BUD
643	3994421FA00F4C2082FC03F70EFE7120	240703 2.0009.AR 9.36.3 BUD	240703 2.0009.643 BUD
644	2782BBFF3D744D429FCFA3CEEC132C39	240703 2.0009.AR 9.36.4 BUD	240703 2.0009.644 BUD
645	C3A4B529FA6241B5B8DFED6CF6F7FC68	240703 2.0009.AR 9.36.5 BUD	240703 2.0009.645 BUD
646	806790EAC11D4EED8829FE8CFFEFBF5F	240703 2.0009.AR 9.53.1 BUD	240703 2.0009.646 BUD
647	F3B9E0731A14437580BCFFFAF6CCA648	240703 2.0009.AR 9.54.1 BUD	240703 2.0009.647 BUD
648	1BD383DE93EB4BC68E58B18DFF1ABCA1	240703 2.0009.AR 9.55.1 BUD	240703 2.0009.648 BUD
649	772886ABDF284E2E876BAAB7E9B79F4E	240703 2.0009.AR 9.58.1 BUD	240703 2.0009.649 BUD
650	8877BFC7E9CB46539A079566AA2BD4D1	240703 2.0009.AR 9.59.1 BUD	240703 2.0009.650 BUD
651	57DECA2C0D8B40E4A903DF91F81D9DB4	240703 2.0009.AR 9.59.2 BUD	240703 2.0009.651 BUD

652	E91EBD979F6A4D9EBAFBE78D4C564091	240703	2.0009.AR	9.59.3	BUD	240703	2.0009.652	BUD
653	C1D9D7B26D4D4CF18C9400701AAE3257	240703	2.0009.AR	9.67.1	BUD	240703	2.0009.653	BUD
654	BE6E521FC5C449B08D735F476EF16635	240703	2.0009.AR	9.67.2	BUD	240703	2.0009.654	BUD
655	ED97B2FA544D4B5BBB1F1EAD7073E557	240703	2.0009.AR	9.67.3	BUD	240703	2.0009.655	BUD
656	F1822262D29C4A3B88FD9918D9B33CF3	240703	2.0009.AR	9.67.4	BUD	240703	2.0009.656	BUD
657	E1B6419DD6D6414DAD87A65EB0C1F947	240703	2.0009.AR	9.67.5	BUD	240703	2.0009.657	BUD
658	64B690A2CDF64C8D98C3B1052F2401BC	240703	2.0009.AR	9.68.1	BUD	240703	2.0009.658	BUD
659	37C8BBC160214033999158B0E6ACF8D7	240703	2.0009.AR	9.115/47.1	BUD	240703	2.0009.659	BUD
660	15D793FD349E4EA0B9D96D78184BA378	240703	2.0009.AR	9.115/47.2	BUD	240703	2.0009.660	BUD
661	97258AA242274FE4A456F055455AEE90	240703	2.0009.AR	9.115/47.3	BUD	240703	2.0009.661	BUD
662	9BB6785825BA411BB14393197FDD5804	240703	2.0009.AR	9.115/47.4	BUD	240703	2.0009.662	BUD
663	011C8955F9134D26A71649F40E2976BA	240703	2.0009.AR	9.115/47.5	BUD	240703	2.0009.663	BUD
664	86E34243D829407CB7270788EE1A0C65	240703	2.0009.AR	9.129/32.1	BUD	240703	2.0009.664	BUD
665	D91DE9BAD46C46D89B4A69E1D00BD8A5	240703	2.0009.AR	9.129/32.2	BUD	240703	2.0009.665	BUD
666	B12EF72C1FF4401DAEF29252F0E735AC	240703	2.0009.AR	9.131/31.1	BUD	240703	2.0009.666	BUD
667	6F418D2131BD4B80946D908FB8610B8B	240703	2.0009.AR	9.131/31.2	BUD	240703	2.0009.667	BUD
668	5CF40CBBC1979459B8054400726BD06BF	240703	2.0009.AR	9.132/31.1	BUD	240703	2.0009.668	BUD
669	FB77521F03BA4E1F95797D5B2E674DF8	240703	2.0009.AR	9.132/31.2	BUD	240703	2.0009.669	BUD
670	3342235005024BEE826E5602EBBA0203	240703	2.0009.AR	9.133/32.1	BUD	240703	2.0009.670	BUD
671	521971C403A9460597537F22E7548C48	240703	2.0009.AR	9.133/32.2	BUD	240703	2.0009.671	BUD
672	5C2BCC52E2CC4592BF7D3C2EDBFBA5D0	240703	2.0009.AR	9.133/32.3	BUD	240703	2.0009.672	BUD
673	EB800558B0984DFA83C70F6E94C3BC21	240703	2.0009.AR	9.175/47.1	BUD	240703	2.0009.673	BUD
674	9D623174FD8E4BDD5929616FB291553	240703	2.0009.AR	9.175/47.2	BUD	240703	2.0009.674	BUD
675	55179F5186204AB8AF9204D211BD0E99	240703	2.0009.AR	9.177/44.1	BUD	240703	2.0009.675	BUD
676	B0EC5678275244EAAD4A85C11EBB2F20	240703	2.0009.AR	9.203/46.1	BUD	240703	2.0009.676	BUD
677	6AC15CFF64644EE6AB4C242CC5C896CE	240703	2.0009.AR	9.203/46.2	BUD	240703	2.0009.677	BUD
678	94DF563270D346B595E8FF01E5E8E659	240703	2.0009.AR	9.203/46.3	BUD	240703	2.0009.678	BUD
679	C1653B74314843189DE7D80E9C16C593	240703	2.0009.AR	9.204/46.1	BUD	240703	2.0009.679	BUD
680	C63754ECF4F74E96B23991E9E22EDAD2	240703	2.0009.AR	9.204/46.2	BUD	240703	2.0009.680	BUD
681	F61943F0169D4B1ABC3DA2079312E092	240703	2.0009.AR	9.206/49.1	BUD	240703	2.0009.681	BUD
682	0AFC6518A34946ED992826D5F63C10CE	240703	2.0009.AR	9.206/49.2	BUD	240703	2.0009.682	BUD
683	CA5B29D72E0445AE89B3D4C406C33E93	240703	2.0009.AR	9.210/30.1	BUD	240703	2.0009.683	BUD
684	65101B8478114381BC1F43CBFAC1C276	240703	2.0009.AR	9.210/30.2	BUD	240703	2.0009.684	BUD
685	8192B399919F48C489B335694AD07A64	240703	2.0009.AR	9.210/30.3	BUD	240703	2.0009.685	BUD
686	DBAA554457814254ABB59D3285B54D16	240703	2.0009.AR	9.210/30.4	BUD	240703	2.0009.686	BUD
687	5CA09677AFEC4479909496C2D7B25051	240703	2.0009.AR	9.215/51.1	BUD	240703	2.0009.687	BUD
688	E8EDF3F2CE0B4285B9634B6C1EC43D85	240703	2.0009.AR	9.215/51.2	BUD	240703	2.0009.688	BUD
689	9C3E53FE72DF465C81BA828D19554A41	240703	2.0009.AR	9.215/51.3	BUD	240703	2.0009.689	BUD
690	59355AE945B2495CB08065B2BE4104F9	240703	2.0009.AR	9.215/51.4	BUD	240703	2.0009.690	BUD
691	19AAF7414A75409098BEF48B7ABC0992	240703	2.0009.AR	9.215/51.5	BUD	240703	2.0009.691	BUD
692	0465ECC93B594872B76A2569CA2463AE	240703	2.0009.AR	9.216/51.1	BUD	240703	2.0009.692	BUD
693	D6E3ED1170E243018D7A7A61DC9DD2E2	240703	2.0009.AR	9.216/51.2	BUD	240703	2.0009.693	BUD
694	69C2584F2B9040D485BE46FD6FB85DA7	240703	2.0009.AR	9.217/64.1	BUD	240703	2.0009.694	BUD
695	62947E07B6B148D28836FE2737DB2A68	240703	2.0009.AR	9.217/64.2	BUD	240703	2.0009.695	BUD
696	E83B1F36437A493EBE8114D723CE86C0	240703	2.0009.AR	9.219/49.1	BUD	240703	2.0009.696	BUD
697	4115263188D049C0940741AF61E0AF4F	240703	2.0009.AR	9.219/49.2	BUD	240703	2.0009.697	BUD
698	0B0ED7AB3D644B7A8A04F8ABBE6469DF	240703	2.0009.AR	9.220/49.1	BUD	240703	2.0009.698	BUD
699	6CDE77203F434AD4848C9A2158776690	240703	2.0009.AR	9.220/49.2	BUD	240703	2.0009.699	BUD
700	1B7570ED8C3744DDAD871E53660A6D6A	240703	2.0009.AR	9.222/30.1	BUD	240703	2.0009.700	BUD
701	29CB5C04A87B4DFBA9DF89832228003A	240703	2.0009.AR	9.222/30.2	BUD	240703	2.0009.701	BUD
702	CAF3232F7B0A40A5B169868B5BA92147	240703	2.0009.AR	9.222/30.3	BUD	240703	2.0009.702	BUD
703	1F435EC04D7D4F12A76CCF2A31F37751	240703	2.0009.AR	9.225/43.1	BUD	240703	2.0009.703	BUD
704	CF5215BCBCE7418F909F5125090BAC03	240703	2.0009.AR	9.226/43.1	BUD	240703	2.0009.704	BUD
705	214A946AFA134717B75050CC5C493772	240703	2.0009.AR	9.228/70.1	BUD	240703	2.0009.705	BUD
706	4C12308573F64AAD8FDF408573137569	240703	2.0009.AR	9.228/70.2	BUD	240703	2.0009.706	BUD
707	22454A5FFA904637BF5E046DEFCC7D70	240703	2.0009.AR	9.228/70.3	BUD	240703	2.0009.707	BUD
708	5011083C19E640B9962670289BFB57D7	240703	2.0009.AR	9.228/70.4	BUD	240703	2.0009.708	BUD
709	744E9B07978A4C60A5A5684D75085ADA	240703	2.0009.AR	9.229/43.1	BUD	240703	2.0009.709	BUD
710	D5FEAF220D7845FC99CFCBA5813538C6	240703	2.0009.AR	9.233/30.1	BUD	240703	2.0009.710	BUD
711	5A6B7E0823044B13BBCBDD17B5E37EA0	240703	2.0009.AR	14-1.54.1	BUD	240703	2.0009.711	BUD
712	695890077A1748AC98659407CD65BE8D	240703	2.0009.AR	14-1.55.1	BUD	240703	2.0009.712	BUD
713	55C4ACCCCD49426DB6653352ECEAC552	240703	2.0009.AR	14-1.55.2	BUD	240703	2.0009.713	BUD
714	EC88AF8248A14DB586E57AD6C5E6E37D	240703	2.0009.AR	14-1.137/52.1	BUD	240703	2.0009.714	BUD
715	F896B3EFBF184896B0DD1F12F25F5675	240703	2.0009.AR	14-1.137/52.2	BUD	240703	2.0009.715	BUD
716	13F53197EEB14379886BC193BB88EF8C	240703	2.0009.AR	14-1.146/77.1	BUD	240703	2.0009.716	BUD
717	48B9208D471B4E8A830BF9BC128469CF	240703	2.0009.AR	14-1.146/77.2	BUD	240703	2.0009.717	BUD

718	ACDC6696DDE5424F884C0DC80D11ACA6	240703	2.0009.AR	14-1.146/77.3	BUD	240703	2.0009.718	BUD
719	BAC8A258A76048F68D6A89C10CBE3F08	240703	2.0009.AR	14-1.179/5.1	BUD	240703	2.0009.719	BUD
720	9FC6467278ED420C8F0308AEB3B724A2	240703	2.0009.AR	14-1.179/5.2	BUD	240703	2.0009.720	BUD
721	064C117F8D914DC2A14E2F6F287131FE	240703	2.0009.AR	14-1.179/5.3	BUD	240703	2.0009.721	BUD
722	8EA624EC8A234900A1DAAE170559DC07	240703	2.0009.AR	14-1.218/111.1	BUD	240703	2.0009.722	BUD
723	8F142C6C856440CA8A3488875F91CD07	240703	2.0009.AR	14-1.218/111.2	BUD	240703	2.0009.723	BUD
724	503473EADDEF4125887954424D65B091	240703	2.0009.AR	14-1.218/111.3	BUD	240703	2.0009.724	BUD
725	756D66F8E2F74D2CB4C3AF1BCE9ED3AB	240703	2.0009.AR	14-1.218/111.4	BUD	240703	2.0009.725	BUD
726	E0A6382053E64A378014E6D4EBECCE58	240703	2.0009.AR	14-1.218/111.5	BUD	240703	2.0009.726	BUD
727	C15A4D7FD7424543870FBA69205D0D72	240703	2.0009.AR	14-1.218/111.6	BUD	240703	2.0009.727	BUD
728	7940A10954934DD59DFBF7A0A16A0A01	240703	2.0009.AR	14-1.218/111.7	BUD	240703	2.0009.728	BUD
729	DBC1DF8CDA434EE686BA5BF6EFF15274	240703	2.0009.AR	14-1.218/111.8	BUD	240703	2.0009.729	BUD
730	6C43AF9F652145E28B3CEB986FC81D62	240703	2.0009.AR	14-1.218/111.9	BUD	240703	2.0009.730	BUD
731	5C27DD41D490423DAF1E29C78C3E5EF0	240703	2.0009.AR	14-1.218/111.10	BUD	240703	2.0009.731	BUD
732	7F5C774B90044040AEAEDE68315951B02	240703	2.0009.AR	14-1.218/111.11	BUD	240703	2.0009.732	BUD
733	A4FEC774751D41BDB247E3F06479EF10	240703	2.0009.AR	14-1.242/46.1	BUD	240703	2.0009.733	BUD
734	19420AC003FA4341B6831552A7BFFF2C	240703	2.0009.AR	14-1.242/46.2	BUD	240703	2.0009.734	BUD
735	5975AE67A0904587A9F8B14B59D4664D	240703	2.0009.AR	14-1.242/46.3	BUD	240703	2.0009.735	BUD
736	95BD55D4C6734F0A8C0E93F8551BE6B9	240703	2.0009.AR	14-1.242/46.4	BUD	240703	2.0009.736	BUD
737	42D4252E0D3F42B69D6CD37E1FE14583	240703	2.0009.AR	14-1.242/46.5	BUD	240703	2.0009.737	BUD
738	B2FA7D9C35924C72962F92271FF750D1	240703	2.0009.AR	14-1.242/46.6	BUD	240703	2.0009.738	BUD
739	85676B2D7D4D4AB7A8C3B5BD4E516282	240703	2.0009.AR	14-1.242/46.7	BUD	240703	2.0009.739	BUD
740	4F10B15425494CE6B3C9295BD85B43CD	240703	2.0009.AR	14-1.246/57.1	BUD	240703	2.0009.740	BUD
741	35EEF2E6182A48EF84455C426FD8DC47	240703	2.0009.AR	14-1.246/57.2	BUD	240703	2.0009.741	BUD
742	8905E41B7B444C8FAFBFB87BB6C68C74	240703	2.0009.AR	14-1.246/57.3	BUD	240703	2.0009.742	BUD
743	3B531CDE1D2242E3836DC4614A9E5A90	240703	2.0009.AR	14-1.248/74.1	BUD	240703	2.0009.743	BUD
744	7B4C032205984B7A94D29BC55708FC41	240703	2.0009.AR	14-1.248/74.2	BUD	240703	2.0009.744	BUD
745	5A04D163E8AF46D9B24CE1E4E0ACDDE6	240703	2.0009.AR	14-1.248/74.3	BUD	240703	2.0009.745	BUD
746	9A5E1D17CDC546CBB05C6F138AE6CF57	240703	2.0009.AR	14-1.248/74.4	BUD	240703	2.0009.746	BUD
747	6F844079080C4475900900146682E0E8	240703	2.0009.AR	14-1.248/74.5	BUD	240703	2.0009.747	BUD
748	169CC37C0C69464CA39FD5713449002D	240703	2.0009.AR	14-1.257/86.1	BUD	240703	2.0009.748	BUD
749	96004BA46CA54CCE947FC86BAFC251E0	240703	2.0009.AR	14-1.257/86.2	BUD	240703	2.0009.749	BUD
750	E45EE8239E1B4D60B5D94A5713DAE3C9	240703	2.0009.AR	14-1.257/86.3	BUD	240703	2.0009.750	BUD
751	9AE664FAA8B542C4BDBAC5E3FA265FD8	240703	2.0009.AR	14-1.257/86.4	BUD	240703	2.0009.751	BUD
752	2AC3CD9EC7834CAEAD6BF619041E7D18	240703	2.0009.AR	14-1.263/91.1	BUD	240703	2.0009.752	BUD
753	CF20E7A0F27A40668B0E04837CA4DAE1	240703	2.0009.AR	14-1.304/20.1	BUD	240703	2.0009.753	BUD
754	ED02874521164606A7F995E940084F27	240703	2.0009.AR	14-1.304/20.2	BUD	240703	2.0009.754	BUD
755	906C343CA34B4E069E92621F9EA0F485	240703	2.0009.AR	14-1.304/20.3	BUD	240703	2.0009.755	BUD
756	B6B52FDF567046938236ED8593972F3	240703	2.0009.AR	14-1.304/20.4	BUD	240703	2.0009.756	BUD
757	45A35E0774034CEAA17E6AF15AC83392	240703	2.0009.AR	14-1.304/20.5	BUD	240703	2.0009.757	BUD
758	35F4CA9A4D774EB58FDEDA827FB5B266	240703	2.0009.AR	14-1.304/20.6	BUD	240703	2.0009.758	BUD
759	DF5E010D9ABA427D8FDE103D5BCBC8D8	240703	2.0009.AR	16-1.86.1	BUD	240703	2.0009.759	BUD
760	9D72EBCB19A442308B3A00D4173D48B5	240703	2.0009.AR	16-1.86.2	BUD	240703	2.0009.760	BUD
761	B39B265B12CC4B36A0BB465854D60C42	240703	2.0009.AR	16-1.86.3	BUD	240703	2.0009.761	BUD
762	0CDA9F4045D045C284A1F78BC7E2135F	240703	2.0009.AR	16-1.87.1	BUD	240703	2.0009.762	BUD
763	614A0FDFDD864D62B43C8AF886964B25	240703	2.0009.AR	16-1.87.2	BUD	240703	2.0009.763	BUD
764	BBC2E4D4D54B44B48E044483CF73D912	240703	2.0009.AR	16-1.191/92.1	BUD	240703	2.0009.764	BUD
765	EEEFB1FF25CD4339A37AF96CAC9D76AE	240703	2.0009.AR	16-1.191/92.2	BUD	240703	2.0009.765	BUD
766	FE59174D9CE741A093970CBBD223BE63	240703	2.0009.AR	16-1.191/92.3	BUD	240703	2.0009.766	BUD
767	0C3D436274384D2993425E968C0A5191	240703	2.0009.AR	16-1.222/18.1	BUD	240703	2.0009.767	BUD
768	4F1E5A7C78054193B7689959B72D1360	240703	2.0009.AR	16-1.222/18.2	BUD	240703	2.0009.768	BUD
769	F32FC7A1662B4A30A75D67259865C0EB	240703	2.0009.AR	16-1.222/18.3	BUD	240703	2.0009.769	BUD
770	13EEB4923DF94F2C95BAB9EE50C043C0	240703	2.0009.AR	16-1.222/18.4	BUD	240703	2.0009.770	BUD
771	F07C30CD34AF4F4D896DB5BE967D8862	240703	2.0009.AR	16-1.223/92.1	BUD	240703	2.0009.771	BUD
772	D8B800A7098B40E3945AFC35701A93E0	240703	2.0009.AR	16-1.223/92.2	BUD	240703	2.0009.772	BUD
773	852B27E4CC1C4A31BAEB3072F5905682	240703	2.0009.AR	16-1.223/92.3	BUD	240703	2.0009.773	BUD
774	D84DA02D28E84F0A9A3EC4FC70AEA423	240703	2.0009.AR	16-1.223/92.4	BUD	240703	2.0009.774	BUD
775	13F88F0A50074E64BE48AE86BF3E33AE	240703	2.0009.AR	16-1.227/92.1	BUD	240703	2.0009.775	BUD
776	43A01583DA6C46EC8EB39C7B571633E6	240703	2.0009.AR	16-1.227/92.2	BUD	240703	2.0009.776	BUD
777	0B273BB8C0824C37975C0849F06300EB	240703	2.0009.AR	16-1.227/92.3	BUD	240703	2.0009.777	BUD
778	3150250006DB4CFFB300EC0DC982998D	240703	2.0009.AR	16-1.231/21.1	BUD	240703	2.0009.778	BUD
779	1DC55132EE9749E2B88CC0B9F2C2137A	240703	2.0009.AR	16-1.231/21.2	BUD	240703	2.0009.779	BUD
780	47FF60CAD5AB4238A6E9C75A59F51FCD	240703	2.0009.AR	16-1.231/21.3	BUD	240703	2.0009.780	BUD
781	8507F985B64B4F38BB34CC7BDC6639F8	240703	2.0009.AR	16-1.246/21.1	BUD	240703	2.0009.781	BUD
782	29D00584398D4AA28420654AA21ED8CF	240703	2.0009.AR	16-1.246/21.2	BUD	240703	2.0009.782	BUD
783	9732A8A5D82246B089921EA24FB0CC3D	240703	2.0009.AR	16-1.246/21.3	BUD	240703	2.0009.783	BUD

784	BB95BAA3AD2F404289046C1C931171A5	240703	2.0009.AR	16-1.246/21.4	BUD	240703	2.0009.784	BUD
785	C02FF9AA91F646E78734083EA306617F	240703	2.0009.AR	16-1.246/21.5	BUD	240703	2.0009.785	BUD
786	69032C1AC39E42899A360BCFD6E221F5	240703	2.0009.AR	16-1.246/21.6	BUD	240703	2.0009.786	BUD
787	80FA9CD7B24A4F33801244A8A8469E83	240703	2.0009.AR	16-1.246/21.7	BUD	240703	2.0009.787	BUD
788	9FD26C1A61094575A36225F36C40C91C	240703	2.0009.AR	16-1.246/21.8	BUD	240703	2.0009.788	BUD
789	71F5BA0D44A945AE9AA2BB372C9BA089	240703	2.0009.AR	16-1.563/92.1	BUD	240703	2.0009.789	BUD
790	F30A621D3578408886E1268291C245F1	240703	2.0009.AR	16-1.563/92.2	BUD	240703	2.0009.790	BUD
791	EFD676764BEC42278B13E36C4B6813B3	240703	2.0009.AR	16-1.563/92.3	BUD	240703	2.0009.791	BUD
792	B4A0F366FC484711914B06E87AA04DAB	240703	2.0009.AR	16-1.564/21.1	BUD	240703	2.0009.792	BUD
793	FAFE67147C1C4D3597AD1C557CD33741	240703	2.0009.AR	16-1.564/21.2	BUD	240703	2.0009.793	BUD
794	32CF9D584014482086A3511BD7392215	240703	2.0009.AR	16-1.564/21.3	BUD	240703	2.0009.794	BUD
795	03C647740DC840539A4015C55F1BFF97	240703	2.0009.AR	16-1.576/92.1	BUD	240703	2.0009.795	BUD
796	959FE253D6C14868A375370906724955	240703	2.0009.AR	16-1.576/92.2	BUD	240703	2.0009.796	BUD
797	BCEB7BE7BB13404D8E8B69034DD553FF	240703	2.0009.AR	16-1.576/92.3	BUD	240703	2.0009.797	BUD
798	3B0A28319CB74930912D3D74E22B6763	240703	2.0009.AR	16-1.576/92.4	BUD	240703	2.0009.798	BUD
799	AD74A7A5C36E4978AA043BE99F16CA10	240703	2.0009.AR	16-1.576/92.5	BUD	240703	2.0009.799	BUD
800	DFBA0FCC64F042B293D07A3E835C9116	240703	2.0009.AR	16-1.577/92.1	BUD	240703	2.0009.800	BUD
801	4F7E50E529714BCC98262922E3FFEFDA	240703	2.0009.AR	2PANOSZÓW.78/36.1	BUD	240703	2.0009.801	BUD
802	5B6305BC5E794EA4A488236A7C8C17CA	240703	2.0009.AR	2PANOSZÓW.78/36.2	BUD	240703	2.0009.802	BUD
803	B01F3315009848A582FBEA5C81AB3867	240703	2.0009.AR	2PANOSZÓW.78/36.3	BUD	240703	2.0009.803	BUD
804	75610DF91DA74D11AD4E6AE5C76E25E6	240703	2.0009.AR	2PANOSZÓW.78/36.4	BUD	240703	2.0009.804	BUD
805	013CF2ED56E448718F1C5D87A069F7AC	240703	2.0009.AR	2PANOSZÓW.78/36.5	BUD	240703	2.0009.805	BUD
806	C3ADB612422C490DAD19C8897DF283C4	240703	2.0009.AR	2PANOSZÓW.78/36.6	BUD	240703	2.0009.806	BUD
807	87ED1A941B03407784C66C5D3FB74EEE	240703	2.0009.AR	2PANOSZÓW.78/36.7	BUD	240703	2.0009.807	BUD
808	066BB87603E44E01ABADD23A1E71BA59	240703	2.0009.AR	2PANOSZÓW.78/36.8	BUD	240703	2.0009.808	BUD
809	B985AF610C1A4524AE2989B5DF6761DD	240703	2.0009.AR	2PANOSZÓW.78/36.9	BUD	240703	2.0009.809	BUD
810	205FB8F4119D40EE85242C13531F86D5	240703	2.0009.AR	2PANOSZÓW.78/36.10	BUD	240703	2.0009.810	BUD
811	815A941493AC4809BD1666E027C9CFD1	240703	2.0009.AR	2PANOSZÓW.79/36.1	BUD	240703	2.0009.811	BUD
812	502FA768C91C491F9BA40A14B0E44B66	240703	2.0009.AR	2PANOSZÓW.79/36.2	BUD	240703	2.0009.812	BUD
813	0A31F797E7444F9BA9502FB579C9A126	240703	2.0009.AR	2PANOSZÓW.79/36.3	BUD	240703	2.0009.813	BUD
814	4ED6423E2ECD4AAC80C078336184ED10	240703	2.0009.AR	2PANOSZÓW.79/36.4	BUD	240703	2.0009.814	BUD
815	D879CBFCC7B34E92B58641656B247462	240703	2.0009.AR	2PANOSZÓW.79/36.5	BUD	240703	2.0009.815	BUD
816	ECF9AB06DFE346CE9E8E9CACAF27CFE2	240703	2.0009.AR	2PANOSZÓW.79/36.6	BUD	240703	2.0009.816	BUD
817	471A5AE1B6184D7C88313B3D59A77F53	240703	2.0009.AR	2PANOSZÓW.79/36.7	BUD	240703	2.0009.817	BUD
818	68E7A58563374ACBA2AB90502E1517F1	240703	2.0009.AR	2PANOSZÓW.79/36.8	BUD	240703	2.0009.818	BUD
819	F5A63BAB17014946A04D24092EB25404	240703	2.0009.AR	2PANOSZÓW.79/36.10	BUD	240703	2.0009.819	BUD
820	800795BA18AB45C997DB2FFE3C8937B2	240703	2.0009.AR	2PANOSZÓW.79/36.11	BUD	240703	2.0009.820	BUD
821	505659E115244B14B461D92249B9DF41	240703	2.0009.AR	2PANOSZÓW.79/36.12	BUD	240703	2.0009.821	BUD
822	01C02048043F44BA96975550D7426ADD	240703	2.0009.AR	2PANOSZÓW.79/36.13	BUD	240703	2.0009.822	BUD
823	6ACAD5B19F684E0D92A46194F4967E23	240703	2.0009.AR	2PANOSZÓW.79/36.14	BUD	240703	2.0009.823	BUD
824	ADD78AF8B5B64DE0ACA3AEA374A394BB	240703	2.0009.AR	2PANOSZÓW.79/36.15	BUD	240703	2.0009.824	BUD
825	4F582DC292264C8BBA52CA34DF49F44A	240703	2.0009.AR	2PANOSZÓW.79/36.16	BUD	240703	2.0009.825	BUD
826	319C1E01FE2742088DCA0701B5C5B87D	240703	2.0009.AR	2PANOSZÓW.79/36.17	BUD	240703	2.0009.826	BUD
827	2E97D27E25424A85A02F1DE50651BCC8	240703	2.0009.AR	2PANOSZÓW.79/36.18	BUD	240703	2.0009.827	BUD
828	2346E655E7ED4F8D8EF2837287519717	240703	2.0009.AR	2PANOSZÓW.79/36.19	BUD	240703	2.0009.828	BUD
829	C36DE28A7A8C40A49D26C0532AAA20BB	240703	2.0009.AR	2PANOSZÓW.79/36.20	BUD	240703	2.0009.829	BUD
830	DC2DB35A845D49BF9BABF115976C697E	240703	2.0009.AR	2PANOSZÓW.79/36.21	BUD	240703	2.0009.830	BUD
831	628DF44446964E7B887C3711A29422A2	240703	2.0009.AR	2PANOSZÓW.79/36.22	BUD	240703	2.0009.831	BUD
832	370470744C8440DB8AA88406D88D83A8	240703	2.0009.AR	2PANOSZÓW.79/36.23	BUD	240703	2.0009.832	BUD
833	7415DC54A3164F74A44EC17BB73B2CC6	240703	2.0009.AR	2PANOSZÓW.79/36.24	BUD	240703	2.0009.833	BUD
834	F0A151B5BDC244269CC698E88B9C24AC	240703	2.0009.AR	2PANOSZÓW.79/36.25	BUD	240703	2.0009.834	BUD
835	9A9E353533B147C18342401EBACFF4C1	240703	2.0009.AR	2PANOSZÓW.79/36.26	BUD	240703	2.0009.835	BUD
836	61A8B6862E64435A8C23D53D07754FE6	240703	2.0009.AR	2PANOSZÓW.79/36.27	BUD	240703	2.0009.836	BUD
837	943112905A404C8E874DAEFC5EC03C40	240703	2.0009.AR	2PANOSZÓW.79/36.28	BUD	240703	2.0009.837	BUD
838	32A072F32AC64F2C9CF9BFA73EDE3B7D	240703	2.0009.AR	2PANOSZÓW.79/36.29	BUD	240703	2.0009.838	BUD
839	1B5A24287E6848D7AA6AB81A544AB0D1	240703	2.0009.AR	2PANOSZÓW.79/36.30	BUD	240703	2.0009.839	BUD
840	055807814AEA4A3EA9E8EB9294366A2B	240703	2.0009.AR	2PANOSZÓW.79/36.31	BUD	240703	2.0009.840	BUD
841	494F2E3015B34B0DAEE85ECA3C83EDF	240703	2.0009.AR	2PANOSZÓW.79/36.32	BUD	240703	2.0009.841	BUD
842	6EFADF34687E45A2A071FD234CF74777	240703	2.0009.AR	2PANOSZÓW.79/36.33	BUD	240703	2.0009.842	BUD
843	BBEDAEEAE63DB4345B4675426DB533E2D	240703	2.0009.AR	2PANOSZÓW.79/36.34	BUD	240703	2.0009.843	BUD
844	172989FE804046ECA9E6B988BE6EAC41	240703	2.0009.AR	2PANOSZÓW.79/36.35	BUD	240703	2.0009.844	BUD
845	858A2ABD12954E0D2993510AD5E347050	240703	2.0009.AR	2PANOSZÓW.79/36.36	BUD	240703	2.0009.845	BUD
846	EE16F66CAD8D4D5798FE0E58C9EA4249	240703	2.0009.AR	2PANOSZÓW.79/36.37	BUD	240703	2.0009.846	BUD
847	21B7733B949E4DE1B28866222E508562	240703	2.0009.AR	2PANOSZÓW.79/36.38	BUD	240703	2.0009.847	BUD
848	29337CC55F8E47C09C3E443D42819C25	240703	2.0009.AR	2PANOSZÓW.79/36.39	BUD	240703	2.0009.848	BUD
849	E9C389E445A74146843B95C2F1C8A01D	240703	2.0009.AR	2PANOSZÓW.79/36.40	BUD	240703	2.0009.849	BUD

850	4F6E5235551C401FA47AED5EA09DFA7A	240703	2.0009.AR	2PANOSZÓW.79/36.41	BUD	240703	2.0009.850	BUD
851	0BEACBDF1C2E4BCDB74732E97FA9BAF7	240703	2.0009.AR	2PANOSZÓW.79/36.42	BUD	240703	2.0009.851	BUD
852	5C30425994404697ACC641153B0C8443	240703	2.0009.AR	2PANOSZÓW.79/36.43	BUD	240703	2.0009.852	BUD
853	C8E3147FF4A74DB49E44DAEF50845849	240703	2.0009.AR	2PANOSZÓW.79/36.44	BUD	240703	2.0009.853	BUD
854	FDAFF2B01A074B0A92A3A0A3593122FC	240703	2.0009.AR	2PANOSZÓW.79/36.45	BUD	240703	2.0009.854	BUD
855	0C2A4B4AC7C4447AB50EABA2EF64CB3F	240703	2.0009.AR	2PANOSZÓW.79/36.46	BUD	240703	2.0009.855	BUD
856	C90C16D9169B4416AB19B9AF159C3A67	240703	2.0009.AR	4MOLNA.14.1	BUD	240703	2.0009.856	BUD
857	2D1B116E32E64C51A9FBA1F5EE1CEADD	240703	2.0009.AR	4MOLNA.22.1	BUD	240703	2.0009.857	BUD
858	8B0DC7D675244AC89BB8B8BA064C48E6	240703	2.0009.AR	4MOLNA.22.2	BUD	240703	2.0009.858	BUD
859	DB6212DD85384EC6A306591BC221AE34	240703	2.0009.AR	4MOLNA.22.3	BUD	240703	2.0009.859	BUD
860	A04D4D48BFA04768AC61AF1E49670B3C	240703	2.0009.AR	4MOLNA.22.4	BUD	240703	2.0009.860	BUD
861	906CB081ED254D3F86FDD107D0B75019	240703	2.0009.AR	4MOLNA.27.1	BUD	240703	2.0009.861	BUD
862	B5FF6B93BC974524B45B1D04E4E97D9E	240703	2.0009.AR	4MOLNA.27.2	BUD	240703	2.0009.862	BUD
863	B44D63FE672440A092AB48D5D3CE602C	240703	2.0009.AR	4MOLNA.28.1	BUD	240703	2.0009.863	BUD
864	335E0F99EE094428AFE522024332F93E	240703	2.0009.AR	4MOLNA.28.2	BUD	240703	2.0009.864	BUD
865	2EF36B89AC8B4F28993CCFD8D0686439	240703	2.0009.AR	4MOLNA.47/10.1	BUD	240703	2.0009.865	BUD
866	1825ECBAC6CB48C1ADCE382CC1D3F100	240703	2.0009.AR	4MOLNA.47/10.2	BUD	240703	2.0009.866	BUD
867	8DF33244B46A44FB9665EE9CF3BBD6A8	240703	2.0009.AR	4MOLNA.48/10.1	BUD	240703	2.0009.867	BUD
868	443485B4B5194B54A6EF1DE4F4AC97F3	240703	2.0009.AR	4MOLNA.60/37.1	BUD	240703	2.0009.868	BUD
869	6D51AE38B887441AA73023BD02210D97	240703	2.0009.AR	4MOLNA.61/37.1	BUD	240703	2.0009.869	BUD
870	406FDD1E6C4A465BBB6AF3926E41645A	240703	2.0009.AR	4MOLNA.61/37.2	BUD	240703	2.0009.870	BUD
871	315F57C6CE1646EA818A8A9789620FFA	240703	2.0009.AR	4MOLNA.81/13.1	BUD	240703	2.0009.871	BUD
872	D58BF0560F64430D989563B9B24585AC	240703	2.0009.AR	4MOLNA.83/13.1	BUD	240703	2.0009.872	BUD
873	84B74B608F74490FBE45B542F05A5894	240703	2.0009.AR	4MOLNA.84/13.1	BUD	240703	2.0009.873	BUD
874	7C24797F06E6463A965AE23672E14BB3	240703	2.0009.AR	4MOLNA.84/13.2	BUD	240703	2.0009.874	BUD
875	414D7988EA1248FD8BC87A706126AE09	240703	2.0009.AR	4MOLNA.84/13.3	BUD	240703	2.0009.875	BUD
876	17CF6AC39D7D406B997FD7DF90CAC628	240703	2.0009.AR	4MOLNA.84/13.4	BUD	240703	2.0009.876	BUD
877	2DBECEFFBFB447058E843A9180DAD6EB	240703	2.0009.AR	4MOLNA.85/13.1	BUD	240703	2.0009.877	BUD
878	B33C68C86F414D57A53E3C6F4F4BF822	240703	2.0009.AR	11MOLNA.20.1	BUD	240703	2.0009.878	BUD
879	2DAB034702314B3D8BDC91C091ECB18E	240703	2.0009.AR	11MOLNA.20.2	BUD	240703	2.0009.879	BUD
880	6EE4E4AAC691465BB9C3FD4D4255FA9B	240703	2.0009.AR	11MOLNA.21.1	BUD	240703	2.0009.880	BUD
881	986523EC474841E88D4EE58F179B9BB0	240703	2.0009.AR	10.61.1	BUD	240703	2.0009.881	BUD
882	F8D0CAE27AEC4147B18C93347C1350D1	240703	2.0009.AR	10.65.1	BUD	240703	2.0009.882	BUD
883	62162CDB41D74833AB168D2E5798E64E	240703	2.0009.AR	10.68.1	BUD	240703	2.0009.883	BUD
884	03C4BC716CE04EB3B3593E6C82BE8B89	240703	2.0009.AR	10.68.2	BUD	240703	2.0009.884	BUD
885	F69B90FD0E54472AA28120C2D96DF636	240703	2.0009.AR	10.68.3	BUD	240703	2.0009.885	BUD
886	41F4904B4EC9493EAD89FE003DCE481C	240703	2.0009.AR	10.68.4	BUD	240703	2.0009.886	BUD
887	76B8E965A56A4B4A9709AC0744A8F020	240703	2.0009.AR	10.68.5	BUD	240703	2.0009.887	BUD
888	A1493ED138A2424C9828145DF7E67D98	240703	2.0009.AR	10.72.1	BUD	240703	2.0009.888	BUD
889	2695BE3A2ABB4A39A982501F64F37C88	240703	2.0009.AR	10.72.2	BUD	240703	2.0009.889	BUD
890	6BAD27F5BB8D4A35B3C67422D0FE7190	240703	2.0009.AR	10.72.3	BUD	240703	2.0009.890	BUD
891	621DB170791548ACADB8EC35D36B2512	240703	2.0009.AR	10.72.4	BUD	240703	2.0009.891	BUD
892	2A2B2F1ED0C04666B68FF66BE8185BA5	240703	2.0009.AR	10.73.1	BUD	240703	2.0009.892	BUD
893	EA2431B2CCDE4A2FA19E98B3FAB8D014	240703	2.0009.AR	10.75.1	BUD	240703	2.0009.893	BUD
894	4F6E6F663FD74954A8A441209AB27D95	240703	2.0009.AR	10.75.2	BUD	240703	2.0009.894	BUD
895	1587A1BA151A4945A5DBF32A54350422	240703	2.0009.AR	10.77.1	BUD	240703	2.0009.895	BUD
896	9915D17AA5624BF59BEB52F760B5BBC8	240703	2.0009.AR	10.81.1	BUD	240703	2.0009.896	BUD
897	D4F9DAFB7C9E4CACBD7F4E925A9A36AB	240703	2.0009.AR	10.81.2	BUD	240703	2.0009.897	BUD
898	A098F28C77CD43AB993660F09F4329AC	240703	2.0009.AR	10.81.3	BUD	240703	2.0009.898	BUD
899	CCA3A05E501A45C299D6B377CC70FA39	240703	2.0009.AR	10.81.4	BUD	240703	2.0009.899	BUD
900	DAFDCD911EEA4A6EAFE1E868F43FA187	240703	2.0009.AR	10.81.5	BUD	240703	2.0009.900	BUD
901	6C2722B004CE4A938430B5C286197CAA	240703	2.0009.AR	10.81.6	BUD	240703	2.0009.901	BUD
902	8D05AF35ACB54E7089FA4B726F69815A	240703	2.0009.AR	10.82.1	BUD	240703	2.0009.902	BUD
903	BA676CFF08AD46AFA5184F6326452DF7	240703	2.0009.AR	10.86.1	BUD	240703	2.0009.903	BUD
904	21E5D51752D149F99D18B48DC4A9CEB8	240703	2.0009.AR	10.86.2	BUD	240703	2.0009.904	BUD
905	E69F23615C9D475F8708A6321C11CA9F	240703	2.0009.AR	10.97/59.1	BUD	240703	2.0009.905	BUD
906	75CE188CAAF246E99AD6E82B1A4E5D17	240703	2.0009.AR	10.97/59.2	BUD	240703	2.0009.906	BUD
907	A323B1A8D7DF44CD992A156CC22761F7	240703	2.0009.AR	10.97/59.3	BUD	240703	2.0009.907	BUD
908	F0D92256AD7A4DE2BA19F0A7428861BE	240703	2.0009.AR	10.97/59.4	BUD	240703	2.0009.908	BUD
909	F8A55A2D87EE4E7C96E9F01893ABCD6B	240703	2.0009.AR	10.97/59.5	BUD	240703	2.0009.909	BUD
910	E1867022545342698EFE14706FFDAAA0	240703	2.0009.AR	10.97/59.6	BUD	240703	2.0009.910	BUD
911	747117B3DE51456CB40747CADAE7A734	240703	2.0009.AR	10.122/14.1	BUD	240703	2.0009.911	BUD
912	D30791ACBF28443D83FF0A64578ABF5	240703	2.0009.AR	10.122/14.2	BUD	240703	2.0009.912	BUD
913	80EAF5FF50DA94AECB32A0616493AF828	240703	2.0009.AR	10.122/14.3	BUD	240703	2.0009.913	BUD
914	D8B9C46161494F508C3394135A5FB448	240703	2.0009.AR	10.122/14.4	BUD	240703	2.0009.914	BUD
915	3D454489BE3F4AFB92C719AB7194B669	240703	2.0009.AR	10.122/14.5	BUD	240703	2.0009.915	BUD

916	0957D4BA666B4D908870046BFC9DF72B	240703	2.0009.AR	10.122/14.6	BUD	240703	2.0009.916	BUD
917	DDF2B51424AE4B17AD3AAA4C9DD32A49	240703	2.0009.AR	10.124/74.1	BUD	240703	2.0009.917	BUD
918	5F1FC686BD2A43BA898880BB2499877A	240703	2.0009.AR	10.124/74.2	BUD	240703	2.0009.918	BUD
919	69481386D2484B17B3D1CF12E582929B	240703	2.0009.AR	10.124/74.3	BUD	240703	2.0009.919	BUD
920	7DBA156F801041F1B3E364DBAAED74A9	240703	2.0009.AR	10.124/74.4	BUD	240703	2.0009.920	BUD
921	DA75629A96E044B990129E82A12F0B2B	240703	2.0009.AR	10.125/74.1	BUD	240703	2.0009.921	BUD
922	9FE5D71BE8C040E2908988908BF9C76C	240703	2.0009.AR	10.125/74.2	BUD	240703	2.0009.922	BUD
923	1DA1D85F2C264BCBA8C336F273A84189	240703	2.0009.AR	10.126/59.1	BUD	240703	2.0009.923	BUD
924	4762F8795FA44C43B81A47952F3D23A7	240703	2.0009.AR	10.126/59.2	BUD	240703	2.0009.924	BUD
925	85AD235C96694E62B6E2FD76FE4A591C	240703	2.0009.AR	10.128/60.1	BUD	240703	2.0009.925	BUD
926	9B80134BA8F5453CAF6E7245F09D7A2F	240703	2.0009.AR	10.128/60.2	BUD	240703	2.0009.926	BUD
927	D59B1869CA7D46B5867A3C1432B7FC0E	240703	2.0009.AR	10.135/57.1	BUD	240703	2.0009.927	BUD
928	1B0D6B04283B4BF8894D5609EBD1B4D7	240703	2.0009.AR	10.135/57.2	BUD	240703	2.0009.928	BUD
929	18F8A6EC0C2D42A881065F5C214220F2	240703	2.0009.AR	10.144/79.1	BUD	240703	2.0009.929	BUD
930	84B3E2F787CE476BA74E070CD43CDF69	240703	2.0009.AR	10.144/79.2	BUD	240703	2.0009.930	BUD
931	7AE7A94E13EE4A789C856E9DAAA70732	240703	2.0009.AR	10.145/79.1	BUD	240703	2.0009.931	BUD
932	AFC32E5223A04FEC8920B36020B86E23	240703	2.0009.AR	10.145/79.2	BUD	240703	2.0009.932	BUD
933	41D41CAD5A3F44ADB7FCB784A8FFE0F4	240703	2.0009.AR	10.153/14.1	BUD	240703	2.0009.933	BUD
934	8949106D4B624C27B160D17842E1B1DD	240703	2.0009.AR	10.167/6.1	BUD	240703	2.0009.934	BUD
935	7A833C914979432AA9D1162995E00110	240703	2.0009.AR	10.167/6.2	BUD	240703	2.0009.935	BUD
936	89E5CAFD246348A7BBA2518B0A74A219	240703	2.0009.AR	10.167/6.3	BUD	240703	2.0009.936	BUD
937	88163FECE7074C25B708E52357174856	240703	2.0009.AR	10.170/2.1	BUD	240703	2.0009.937	BUD
938	E71518F2D19441B1B2C980B3FAF73DDE	240703	2.0009.AR	10.171/59.1	BUD	240703	2.0009.938	BUD
939	9DDEC2E675D34D349F0F9FF9FC6ECA5A	240703	2.0009.AR	10.171/59.2	BUD	240703	2.0009.939	BUD
940	157B1C7EB3C84F94A00D817A75B66678	240703	2.0009.AR	10.172/59.1	BUD	240703	2.0009.940	BUD
941	7478D0ACD04342ADA0D77F6DC7C3A970	240703	2.0009.AR	10.172/59.2	BUD	240703	2.0009.941	BUD
942	BF150A51FE95402FB7FB36EBBA8AA2EB	240703	2.0009.AR	10.172/59.3	BUD	240703	2.0009.942	BUD
943	F7075E72792D4C44938C51D3E71B412F	240703	2.0009.AR	10.172/59.4	BUD	240703	2.0009.943	BUD
944	2703C8DFACA74B3F8B6B284B446C926E	240703	2.0009.AR	10.172/59.5	BUD	240703	2.0009.944	BUD
945	F2B0CD16BFA54583B5747F1CBFA051A8	240703	2.0009.AR	10.221/13.1	BUD	240703	2.0009.945	BUD
946	D873F924F8D945FEA9E937493AEED2F7	240703	2.0009.AR	10.222/13.1	BUD	240703	2.0009.946	BUD
947	469FB6DE6F0F48979DE83A3FF05B3E17	240703	2.0009.AR	10.224/9.1	BUD	240703	2.0009.947	BUD
948	0526B86F37E14345BA7DFA9B50E593EE	240703	2.0009.AR	10.224/9.2	BUD	240703	2.0009.948	BUD
949	0A13DA8BC405453BBFC8EDBC85783D5E	240703	2.0009.AR	10.224/9.3	BUD	240703	2.0009.949	BUD
950	27991F87859E4B96AB3420ED5145F227	240703	2.0009.AR	10.224/9.4	BUD	240703	2.0009.950	BUD
951	E375FB8CF690452F86710B35B56A0838	240703	2.0009.AR	10.225/9.1	BUD	240703	2.0009.951	BUD
952	B5955244EAD04929AEC7E18F95580A01	240703	2.0009.AR	10.225/9.2	BUD	240703	2.0009.952	BUD
953	56D8B23EAA9D4795A766BE9AA1BA0777	240703	2.0009.AR	10.225/9.3	BUD	240703	2.0009.953	BUD
954	77BE71C55F1545C38D297F0535E87D4	240703	2.0009.AR	10.226/9.1	BUD	240703	2.0009.954	BUD
955	3D02A48C1D9A49F69F83A26149B35AFB	240703	2.0009.AR	10.226/9.2	BUD	240703	2.0009.955	BUD
956	1EE4DC8BEFEA47D7BDF03E8EF125D7EE	240703	2.0009.AR	10.228/64.1	BUD	240703	2.0009.956	BUD
957	A41F17D6CAC8442FAA6F3B2CFA8EDDC1	240703	2.0009.AR	10.228/64.2	BUD	240703	2.0009.957	BUD
958	EE36E5C6DBA940D098B2D330AABDD8A9	240703	2.0009.AR	10.232/9.1	BUD	240703	2.0009.958	BUD
959	405A29FE04A046EDB149236529EC2CF3	240703	2.0009.AR	10.234/9.1	BUD	240703	2.0009.959	BUD
960	B83CCB5C807C44DD9EAE5EDA16CF26CC	240703	2.0009.AR	10.235/9.1	BUD	240703	2.0009.960	BUD
961	C7818DC9201044068140D95CF9290ADC	240703	2.0009.AR	10.235/9.2	BUD	240703	2.0009.961	BUD
962	672CEF2749EF40D1A3336F8115B6AC36	240703	2.0009.AR	10.237/2.1	BUD	240703	2.0009.962	BUD
963	1194B7465C5A44D8BD521DAC86EA2869	240703	2.0009.AR	10.241/3.1	BUD	240703	2.0009.963	BUD
964	EE7975E84678409B81AB1D1D1FF98723	240703	2.0009.AR	10.242/3.1	BUD	240703	2.0009.964	BUD
965	7BE6E520ABA24A32AF7BB8CF4BD094BD	240703	2.0009.AR	10.242/3.2	BUD	240703	2.0009.965	BUD
966	F973D3AD3B014A2ABE9463CE799CAD75	240703	2.0009.AR	10.242/3.3	BUD	240703	2.0009.966	BUD
967	FE845B0E192D4844891734193B7D4566	240703	2.0009.AR	10.242/3.4	BUD	240703	2.0009.967	BUD
968	F3CC7E621FCC4D87964339E676A8BD4E	240703	2.0009.AR	10.242/3.5	BUD	240703	2.0009.968	BUD
969	F65D0C615A664DABAB79858A20B6CB84	240703	2.0009.AR	10.244/2.1	BUD	240703	2.0009.969	BUD
970	B13C20BA6A9F4E5F8CD955B03AB495B9	240703	2.0009.AR	10.244/2.2	BUD	240703	2.0009.970	BUD
971	778CB26B5BFD4374BDA5E949E0DC98DF	240703	2.0009.AR	10.248/9.1	BUD	240703	2.0009.971	BUD
972	D0A82C8259724DC19E284D0BBB1E1B8C	240703	2.0009.AR	10.248/9.2	BUD	240703	2.0009.972	BUD
973	55D27FEDC2A5422DA4F8087161EE27E0	240703	2.0009.AR	10.249/9.1	BUD	240703	2.0009.973	BUD
974	075470412ACF43D5A95AB09352FB594B	240703	2.0009.AR	10.249/9.2	BUD	240703	2.0009.974	BUD
975	4C39F918B765467988C53655A2323BC1	240703	2.0009.AR	10.252/2.1	BUD	240703	2.0009.975	BUD
976	1329906E025441A8A49A62AD0BCD324A	240703	2.0009.AR	10.252/2.2	BUD	240703	2.0009.976	BUD
977	753A44F8725C4BB385223C2AE4D0D903	240703	2.0009.AR	10.253/2.1	BUD	240703	2.0009.977	BUD
978	0431C0CBE8A947BBB6452670BA8B63C8	240703	2.0009.AR	10.253/2.2	BUD	240703	2.0009.978	BUD
979	19F48247557C45FF9EB744384A9DE67F	240703	2.0009.AR	10.253/2.4	BUD	240703	2.0009.979	BUD
980	91BCB08EE28E4C4483FD884AFDFC7781	240703	2.0009.AR	10.255/6.1	BUD	240703	2.0009.980	BUD
981	470C3A2CD2344FB3969129B40011D516	240703	2.0009.AR	10.255/6.2	BUD	240703	2.0009.981	BUD

982	308C91BF5E424711BAF42D59B3C5FB69	240703 2.0009.AR 10.264/9.1 BUD	240703 2.0009.982 BUD
983	B0926745520946BE9D2A38944EA0A09E	240703 2.0009.AR 10.264/9.2 BUD	240703 2.0009.983 BUD
984	C978C8BD3A3C48C7A2E5EAB9B164ADF5	240703 2.0009.AR 10.266/2.1 BUD	240703 2.0009.984 BUD
985	AEDCD4357D124D819F94A65F33D866D2	240703 2.0009.AR 10.269/6.1 BUD	240703 2.0009.985 BUD
986	101D6FFA43044BCFBACBFDE742FD0B55	240703 2.0009.AR 10.269/6.2 BUD	240703 2.0009.986 BUD
987	C0BD505403E74F13AB20FFFBB33C3D17	240703 2.0009.AR 10.269/6.3 BUD	240703 2.0009.987 BUD
988	9D4AE8C7D00C48968ACB7F010A156030	240703 2.0009.AR 10.269/6.4 BUD	240703 2.0009.988 BUD

Raport lokali z przenumerowanych budynków.

Lp.	Identyfikator	Stary IG5	Nowy IG5
989	2CD27DFBB0E6407FA75C7D0FF4267505	240703 2.0009.AR 9.225/43.1 BUD.1 LOK	240703 2.0009.703 BUD.1 LOK
990	3AD9E1212A1C43CBB531B2B0E5F9880F	240703 2.0009.AR 9.225/43.1 BUD.2 LOK	240703 2.0009.703 BUD.2 LOK
991	EE7153E5F58C4784BE31E6745667146B	240703 2.0009.AR 9.225/43.1 BUD.3 LOK	240703 2.0009.703 BUD.3 LOK