

System Informacji Przestrzennej GEO-INFO Mapa (nr 1536, wyd. 25.3.1.0)
Data sporządzenia: 2025-09-16 12:32:35
Układ współrzędnych: 2000_18 - Układ odniesienia: PL-ETRF2000-2000
Układ wysokościowy: PL-EVRF2007-NH
Baza danych: GI_Lubliniec - (nr 5360004)

Raport przenumrowania budynków.
Systematyki: 240707 2.0009

Lp.	Identyfikator	Stary IG5	Nowy IG5
1	5ED337471F794E558581E19BED542484	240707 2.0009.AR 2.21.1 BUD	240707 2.0009.1 BUD
2	525E6990456D4610B1E99865B36A8F59	240707 2.0009.AR 2.22.1 BUD	240707 2.0009.2 BUD
3	2FADDE1C78F5437FB332090A9F252665	240707 2.0009.AR 2.22.2 BUD	240707 2.0009.3 BUD
4	C4424E066E714A15AFE9374205B3341F	240707 2.0009.AR 2.22.3 BUD	240707 2.0009.4 BUD
5	8454AE53079A49A382AB70ED5D8D79F5	240707 2.0009.AR 2.24.1 BUD	240707 2.0009.5 BUD
6	D0C596285E83448ABB1F63DB94597B22	240707 2.0009.AR 2.24.2 BUD	240707 2.0009.6 BUD
7	83ABE79FEC3E43CFBC09FBE7AD3DA957	240707 2.0009.AR 2.24.3 BUD	240707 2.0009.7 BUD
8	4B0FB3D08BA4424794FB62F5E6E138BE	240707 2.0009.AR 2.25.1 BUD	240707 2.0009.8 BUD
9	AA5E19329E15449DABE8EB6D02343DA9	240707 2.0009.AR 2.25.2 BUD	240707 2.0009.9 BUD
10	51B0108BC58F4F5E93CA242F5F553D9B	240707 2.0009.AR 2.58.1 BUD	240707 2.0009.10 BUD
11	6637DE573AAF44118DD1FC8C0585F906	240707 2.0009.AR 2.58.2 BUD	240707 2.0009.11 BUD
12	915CB0A06BEC4BC98AA0F925B7F5ED1D	240707 2.0009.AR 2.58.3 BUD	240707 2.0009.12 BUD
13	032AC1DA0EBE4BDC8C7694F89D146347	240707 2.0009.AR 2.136/30.1 BUD	240707 2.0009.13 BUD
14	975F9D65539C4C869982462F074617A5	240707 2.0009.AR 2.136/30.2 BUD	240707 2.0009.14 BUD
15	4968F1D28A4640EA937E1950BF3CDBE2	240707 2.0009.AR 2.136/30.3 BUD	240707 2.0009.15 BUD
16	7D6206ABD13A43CEAF59406FC03DA9B9	240707 2.0009.AR 2.136/30.4 BUD	240707 2.0009.16 BUD
17	38E7DF196D7C47B7807E2D8A3576C2C1	240707 2.0009.AR 2.136/30.5 BUD	240707 2.0009.17 BUD
18	79CC1BF9ED434310AA844C1670E4598B	240707 2.0009.AR 2.136/30.6 BUD	240707 2.0009.18 BUD
19	FB15A7CEAE04422CB3FA1C9D59EB0548	240707 2.0009.AR 2.169/27.1 BUD	240707 2.0009.19 BUD
20	B6117743466445CC93809EDB97F1F9E6	240707 2.0009.AR 2.169/27.2 BUD	240707 2.0009.20 BUD
21	1D193EAA991A49E697935755AF63A10B	240707 2.0009.AR 2.169/27.4 BUD	240707 2.0009.21 BUD
22	AD7256796BE840B68D5FC1675666843F	240707 2.0009.AR 2.183/27.1 BUD	240707 2.0009.22 BUD
23	DFB2116E91EA4042ABAC1B5170EB6786	240707 2.0009.AR 2.184/27.1 BUD	240707 2.0009.23 BUD
24	268D0973BA594CDBB01DC8F30E082597	240707 2.0009.AR 2.184/27.2 BUD	240707 2.0009.24 BUD
25	9D77AC8BEDCE48E491C0E14F2DDC5623	240707 2.0009.AR 2.184/27.3 BUD	240707 2.0009.25 BUD
26	AF2F4CB63BF040E792847B249EB0D322	240707 2.0009.AR 2.184/27.4 BUD	240707 2.0009.26 BUD
27	3B50947E192845FA9D8DD0313465C2FE	240707 2.0009.AR 2.184/27.5 BUD	240707 2.0009.27 BUD
28	F11BEA1B1E7C4445A854DEBB25956900	240707 2.0009.AR 2.184/27.6 BUD	240707 2.0009.28 BUD
29	B6FE8347E32B4EA2A70675B085F99514	240707 2.0009.AR 2.219/49.1 BUD	240707 2.0009.29 BUD
30	A96926BF09314C4F86F3B215060D9B44	240707 2.0009.AR 2.219/49.2 BUD	240707 2.0009.30 BUD
31	CC993F6DD36B41588C890BF8CF36DE32	240707 2.0009.AR 2.219/49.3 BUD	240707 2.0009.31 BUD
32	B1E0F1BCDAD94A78BBEB4C42D96CEB7F	240707 2.0009.AR 2.221/57.1 BUD	240707 2.0009.32 BUD
33	962AD27CB14542E7811CA3C8F78FD894	240707 2.0009.AR 2.221/57.2 BUD	240707 2.0009.33 BUD
34	B42FCE02E71DA1B280B51967B33D6E33	240707 2.0009.AR 2.223/57.1 BUD	240707 2.0009.34 BUD
35	187BD9BF745C413C9CC96643125D5C26	240707 2.0009.AR 2.224/57.1 BUD	240707 2.0009.35 BUD
36	A4C4D2BA1514431EB571047F434D5554	240707 2.0009.AR 2.224/57.2 BUD	240707 2.0009.36 BUD
37	313793C2729140C1AB8F4547BC814C11	240707 2.0009.AR 2.226/23.1 BUD	240707 2.0009.37 BUD
38	628C299B3A1B4355A69AE2E96A36CE90	240707 2.0009.AR 2.226/23.2 BUD	240707 2.0009.38 BUD
39	E0C4DC510C624AA2BA68954D35A00661	240707 2.0009.AR 2.226/23.3 BUD	240707 2.0009.39 BUD
40	94CE20EAB27A48C98DD84A3314942853	240707 2.0009.AR 2.253/29.1 BUD	240707 2.0009.40 BUD
41	C8A87DB140BA43CF90702E116280E8BE	240707 2.0009.AR 2.258/20.1 BUD	240707 2.0009.41 BUD
42	F05A314BB8C3462FBB7C3CAB190E8B2F	240707 2.0009.AR 2.260/20.1 BUD	240707 2.0009.42 BUD
43	ASF1FEDBFDCB4AB79710CDFEE33A73E6	240707 2.0009.AR 2.261/29.1 BUD	240707 2.0009.43 BUD
44	7BAD57163CBA48068B0D253C70B8748D	240707 2.0009.AR 3.15.1 BUD	240707 2.0009.44 BUD
45	ED837B622CC945EB930A15B593AD1030	240707 2.0009.AR 3.15.3 BUD	240707 2.0009.45 BUD
46	0790AC8301574F8AA52CD09F5A96A10E	240707 2.0009.AR 3.15.6 BUD	240707 2.0009.46 BUD
47	C92BFA8D7F214CB2BB708B9F712BFDD9	240707 2.0009.AR 3.25.2 BUD	240707 2.0009.47 BUD
48	99D406C08DF94689B51D0C9CE16B494B	240707 2.0009.AR 3.25.3 BUD	240707 2.0009.48 BUD
49	EDB40083E7794D8C98583AEE2A16E8F7	240707 2.0009.AR 3.25.4 BUD	240707 2.0009.49 BUD
50	43019B3ED6264E10A71B3400CC5231A6	240707 2.0009.AR 3.25.5 BUD	240707 2.0009.50 BUD
51	17FC20EDCBF24F9BA87AECDA6DA4AF22	240707 2.0009.AR 3.25.6 BUD	240707 2.0009.51 BUD
52	5D8E85A6191C47879EFBB7733C33967C	240707 2.0009.AR 3.28.1 BUD	240707 2.0009.52 BUD
53	21C3E888645948E5BF397DF3EDFD416B	240707 2.0009.AR 3.29.1 BUD	240707 2.0009.53 BUD
54	0C95043AB06A43C9BB96886D90690A82	240707 2.0009.AR 3.29.2 BUD	240707 2.0009.54 BUD
55	F73124B42CDE470BBC3DEE9A15148902	240707 2.0009.AR 3.29.3 BUD	240707 2.0009.55 BUD
56	C26B55B07C5E4393B4B0F9E990BBC63D	240707 2.0009.AR 3.29.4 BUD	240707 2.0009.56 BUD
57	70FF0A29CE804D64B18A4BCD3600C5E1	240707 2.0009.AR 3.29.5 BUD	240707 2.0009.57 BUD
58	22D71A10E1F74413A6F6D42D3F451692	240707 2.0009.AR 3.34.1 BUD	240707 2.0009.58 BUD
59	7F4DC6E593304EC2A687C44335524A81	240707 2.0009.AR 3.39.1 BUD	240707 2.0009.59 BUD
60	480F8F0377E34D16A97FFEE11868650E	240707 2.0009.AR 3.39.2 BUD	240707 2.0009.60 BUD
61	FB7EBFD87D644684861A674CC4A4FB27	240707 2.0009.AR 3.40.1 BUD	240707 2.0009.61 BUD
62	F5222EA2C1674EF7AF45D23A56202C22	240707 2.0009.AR 3.46.1 BUD	240707 2.0009.62 BUD
63	8544067132F8476DA6286A7B40108192	240707 2.0009.AR 3.46.2 BUD	240707 2.0009.63 BUD
64	ADE36FAA3D7C4D06AD04DDE43A21113C	240707 2.0009.AR 3.46.3 BUD	240707 2.0009.64 BUD
65	71A7A919EBF94013B3C583E8972CD650	240707 2.0009.AR 3.47.1 BUD	240707 2.0009.65 BUD
66	DE87261D4B6B425987D1CB371558EC61	240707 2.0009.AR 3.47.2 BUD	240707 2.0009.66 BUD
67	BDE71F7D7AF243CDA60EA4D9E2585AC6	240707 2.0009.AR 3.48.1 BUD	240707 2.0009.67 BUD
68	DB7D0EAA81964DB7A0B2C29A9A8C8051	240707 2.0009.AR 3.48.2 BUD	240707 2.0009.68 BUD
69	C44AA46F1C5F4B9485988DD7EDD6ABEC	240707 2.0009.AR 3.71.1 BUD	240707 2.0009.69 BUD

70	CB29882063C342A6B1CEE593338B3BE3	240707_2.0009.AR_3.71.2_BUD	240707_2.0009.70_BUD
71	B2C52237D1064C81A0423027E9FFDC4F	240707_2.0009.AR_3.71.3_BUD	240707_2.0009.71_BUD
72	8A01643C48B24660A488444C416C11AC	240707_2.0009.AR_3.71.4_BUD	240707_2.0009.72_BUD
73	C9FA9A7C163847FDB89BA3B3522CB9DD	240707_2.0009.AR_3.135/14.1_BUD	240707_2.0009.73_BUD
74	B5700BA6B19247F3AA78FFD3EEA4F0BC	240707_2.0009.AR_3.136/14.1_BUD	240707_2.0009.74_BUD
75	9AF6352F87534E25B645CFD9AD7CDF98	240707_2.0009.AR_3.137/13.1_BUD	240707_2.0009.75_BUD
76	A360E9A0ACC74E89B4C6DACF5007C3B6	240707_2.0009.AR_3.137/13.2_BUD	240707_2.0009.76_BUD
77	78BF1668BBF148AEB5469ADF6F7542FE	240707_2.0009.AR_3.140/19.2_BUD	240707_2.0009.77_BUD
78	841E7DD03A7E478E8D0F7C1A2129CAEA	240707_2.0009.AR_3.150/30.1_BUD	240707_2.0009.78_BUD
79	1542389665644C79916CC31F161CB9FE	240707_2.0009.AR_3.150/30.2_BUD	240707_2.0009.79_BUD
80	02A271F4ADE84EA0BB9AAD893DB2B3D5	240707_2.0009.AR_3.150/30.3_BUD	240707_2.0009.80_BUD
81	FA24A0AF4DE34CDE841F2CA3F62AD398	240707_2.0009.AR_3.150/30.4_BUD	240707_2.0009.81_BUD
82	62B2FD2B01E94C16943D43BC86369C74	240707_2.0009.AR_3.152/30.1_BUD	240707_2.0009.82_BUD
83	A8F5D335F36C44F791F0AAC964BD62C6	240707_2.0009.AR_3.152/30.2_BUD	240707_2.0009.83_BUD
84	5816322A906B495DB4E5D1B2F21A33B1	240707_2.0009.AR_3.152/30.3_BUD	240707_2.0009.84_BUD
85	2FC228A1521243E38F07D6CCF1872EE2	240707_2.0009.AR_3.153/32.1_BUD	240707_2.0009.85_BUD
86	3E0A9772210C47A796232DFC90B9427F	240707_2.0009.AR_3.158/64.1_BUD	240707_2.0009.86_BUD
87	62C2FC27AC004EA8899FF6E99AD70050	240707_2.0009.AR_3.158/64.2_BUD	240707_2.0009.87_BUD
88	61AD90E5A73E46D49DCB3D4FCCC8D953	240707_2.0009.AR_3.158/64.3_BUD	240707_2.0009.88_BUD
89	4CB9713DE4ED4116B7DFF06F215EAA7B	240707_2.0009.AR_3.158/64.4_BUD	240707_2.0009.89_BUD
90	C8B96EA712EF437F9C58C5EF596CDDDB9	240707_2.0009.AR_3.194/36.1_BUD	240707_2.0009.90_BUD
91	2FBA2B1ECB9E4C13960EB354207C5A0B	240707_2.0009.AR_3.195/36.1_BUD	240707_2.0009.91_BUD
92	5CF7CFEB8FBB4C599548EF71E06DF8B6	240707_2.0009.AR_3.195/36.2_BUD	240707_2.0009.92_BUD
93	B528D1F07C0C41C180DC6BA9394647B7	240707_2.0009.AR_3.198/26.1_BUD	240707_2.0009.93_BUD
94	1969BF8172C94C3BA3A6ABC179CAFB8A	240707_2.0009.AR_3.198/26.2_BUD	240707_2.0009.94_BUD
95	35B1AB2BA0BC46F5A79367A0BF5F899A	240707_2.0009.AR_3.198/26.3_BUD	240707_2.0009.95_BUD
96	58F60EC5B6264F38A9F78372953F78C1	240707_2.0009.AR_3.204/55.1_BUD	240707_2.0009.96_BUD
97	AA6DD86B10074819A5D345DEE37AB069	240707_2.0009.AR_3.205/54.1_BUD	240707_2.0009.97_BUD
98	78D853FF3535471F9F026A9F29B94799	240707_2.0009.AR_3.205/54.2_BUD	240707_2.0009.98_BUD
99	87A2E357CF464F29AE9389A7E3846769	240707_2.0009.AR_3.205/54.3_BUD	240707_2.0009.99_BUD
100	9831AE4F17124B49A4AE09829476CE6D	240707_2.0009.AR_3.205/54.4_BUD	240707_2.0009.100_BUD
101	217E6BA12E8747C280FD12E01FCE55F2	240707_2.0009.AR_3.206/55.1_BUD	240707_2.0009.101_BUD
102	C55C20F036524067B98E9AE5204EAAEB	240707_2.0009.AR_3.206/55.2_BUD	240707_2.0009.102_BUD
103	1B1CC510FFBC418FB351EC79100B85C3	240707_2.0009.AR_3.227/30.1_BUD	240707_2.0009.103_BUD
104	DAACF0B5BFCC4C5FA07DFF39F97496D5	240707_2.0009.AR_3.228/98.1_BUD	240707_2.0009.104_BUD
105	025898C6B48C446FB49F6662AFB55303	240707_2.0009.AR_3.228/98.2_BUD	240707_2.0009.105_BUD
106	9C59F2B9D05F47A1821D814A441A6FDE	240707_2.0009.AR_3.229/97.1_BUD	240707_2.0009.106_BUD
107	792D7DE26E5B4C4D8BA2B302603A09B4	240707_2.0009.AR_3.229/97.2_BUD	240707_2.0009.107_BUD
108	9EC8C2FEE1F448F5B01FE4A4DD03F722	240707_2.0009.AR_3.229/97.3_BUD	240707_2.0009.108_BUD
109	38FB9611A613495DA266F8B4B18D7537	240707_2.0009.AR_3.230/94.1_BUD	240707_2.0009.109_BUD
110	8A6588E4A82042EE94972EDAC263340F	240707_2.0009.AR_3.230/94.2_BUD	240707_2.0009.110_BUD
111	64FD738709264AC38C7B694373AF7526	240707_2.0009.AR_3.230/94.3_BUD	240707_2.0009.111_BUD
112	FEC3658E5E104D51B8C122807FEAFBD4	240707_2.0009.AR_3.230/94.4_BUD	240707_2.0009.112_BUD
113	B7BB82103F8C46AD8477132EC094D200	240707_2.0009.AR_3.231/91.1_BUD	240707_2.0009.113_BUD
114	53FB728786864F8FBC32C5C036DE7323	240707_2.0009.AR_3.231/91.2_BUD	240707_2.0009.114_BUD
115	E14157EB16AA4A34B8B244CAA21076B4	240707_2.0009.AR_3.231/91.3_BUD	240707_2.0009.115_BUD
116	CD9468C295444BE5A9F086F90EF5331F	240707_2.0009.AR_3.231/91.4_BUD	240707_2.0009.116_BUD
117	E9766B7877D044CD89D7C2CF7AC7A3CE4	240707_2.0009.AR_3.231/91.5_BUD	240707_2.0009.117_BUD
118	03E0DF31487A40C28303D763319B1755	240707_2.0009.AR_3.232/89.1_BUD	240707_2.0009.118_BUD
119	57D277005AC143928841E9B37F8D2844	240707_2.0009.AR_3.232/89.2_BUD	240707_2.0009.119_BUD
120	50E448783AE8438A9D5BF097C926847E	240707_2.0009.AR_3.232/89.3_BUD	240707_2.0009.120_BUD
121	F2EEF5022E0942BF96CE36EF24A2942A	240707_2.0009.AR_3.232/89.4_BUD	240707_2.0009.121_BUD
122	8CD9377E68F74B17BDED73B00D9F37DC	240707_2.0009.AR_3.232/89.5_BUD	240707_2.0009.122_BUD
123	87ECE764A19E46DB8DFF73311A19BCB8	240707_2.0009.AR_3.232/89.6_BUD	240707_2.0009.123_BUD
124	8D6E952953F54A139F60A88A230C384D	240707_2.0009.AR_3.233/86.1_BUD	240707_2.0009.124_BUD
125	03ED8415BC69435AAA307821AFD29971	240707_2.0009.AR_3.233/86.2_BUD	240707_2.0009.125_BUD
126	47C5641EF49E4E338C629E91E0A94CB6	240707_2.0009.AR_3.233/86.3_BUD	240707_2.0009.126_BUD
127	9AD0977AF9EF4F098A5990C64A82D5A8	240707_2.0009.AR_3.233/86.4_BUD	240707_2.0009.127_BUD
128	F7BD41AB516A40F6B1DE7EA17EBB8B5B	240707_2.0009.AR_3.233/86.5_BUD	240707_2.0009.128_BUD
129	656D21A1DC694315A106D83142F70F40	240707_2.0009.AR_3.233/86.6_BUD	240707_2.0009.129_BUD
130	3FB5C336270B4A6C97CBD20A07CC5E11	240707_2.0009.AR_3.234/57.1_BUD	240707_2.0009.130_BUD
131	75AFDE762CEB4232B09DE783B9586904	240707_2.0009.AR_3.234/57.2_BUD	240707_2.0009.131_BUD
132	D6C7DA3B3BC5415CA941F5EFA290A7A3	240707_2.0009.AR_3.234/57.3_BUD	240707_2.0009.132_BUD
133	9C76C38C2AB343519B50CDE26127A68D	240707_2.0009.AR_3.234/78.1_BUD	240707_2.0009.133_BUD
134	A6B45238BF4042D09D70A6773D5D1E72	240707_2.0009.AR_3.234/78.2_BUD	240707_2.0009.134_BUD
135	EB89DFEA283C44328F671B622FD0DBB7	240707_2.0009.AR_3.234/78.3_BUD	240707_2.0009.135_BUD
136	CF1A7B369BB340AD9C06C053F3C83E71	240707_2.0009.AR_3.234/78.4_BUD	240707_2.0009.136_BUD
137	26966EA668474E9091D74560A6190671	240707_2.0009.AR_3.234/78.5_BUD	240707_2.0009.137_BUD
138	FF8E9336836445348D239305DCE1EBF7	240707_2.0009.AR_3.234/78.6_BUD	240707_2.0009.138_BUD
139	DBFEF7E1B3024ED0971B8E46B9AE16E7	240707_2.0009.AR_3.235/27.1_BUD	240707_2.0009.139_BUD
140	6BDFDD6ADEBB4BCF90338F063DEB109B	240707_2.0009.AR_3.235/27.2_BUD	240707_2.0009.140_BUD
141	B51CD8DCFBAA4460A59D9B14B3209551	240707_2.0009.AR_3.235/27.3_BUD	240707_2.0009.141_BUD
142	F022416EFF354AEDBE9992CE80873ABD	240707_2.0009.AR_3.235/75.1_BUD	240707_2.0009.142_BUD
143	42BD3C475F674008B4B8807CF8896960	240707_2.0009.AR_3.235/75.2_BUD	240707_2.0009.143_BUD
144	922A3412946E4817803CA9D72E3431D1	240707_2.0009.AR_3.235/75.3_BUD	240707_2.0009.144_BUD
145	D674DA35B0CA466C8BC367BCEE856A05	240707_2.0009.AR_3.235/75.4_BUD	240707_2.0009.145_BUD
146	4B1C50645ADA4ACDB24DE311C625EC50	240707_2.0009.AR_3.235/75.5_BUD	240707_2.0009.146_BUD
147	971404CBCEB847BA8AD1D4EAB96D21B5	240707_2.0009.AR_3.235/75.6_BUD	240707_2.0009.147_BUD

148	03B1FB3A510A49ED8522617F10274D64	240707_2.0009.AR_3.236/74.1_BUD	240707_2.0009.148_BUD
149	3DBBF3FD4F844A62B65B54F1A49F1A1D	240707_2.0009.AR_3.236/74.2_BUD	240707_2.0009.149_BUD
150	ED6ECFD26ABF4D6196BBBC904F249EB8	240707_2.0009.AR_3.236/74.3_BUD	240707_2.0009.150_BUD
151	FE71FD84C9084F0F8782DEF80BB811A4	240707_2.0009.AR_3.239/16.1_BUD	240707_2.0009.151_BUD
152	30ACA0F0695A47688EBAC794C4886701	240707_2.0009.AR_3.249/57.1_BUD	240707_2.0009.152_BUD
153	EE827CD1CAE34A9A8F2E0AEE71866195	240707_2.0009.AR_3.249/57.2_BUD	240707_2.0009.153_BUD
154	1EAF2FA34E614067AD238B8572C59670	240707_2.0009.AR_3.251/99.1_BUD	240707_2.0009.154_BUD
155	4F2068F9E4CF498699CCFA25E2395F89	240707_2.0009.AR_3.251/99.2_BUD	240707_2.0009.155_BUD
156	C65FB88382CD4E669BA4A7B227B3DF65	240707_2.0009.AR_3.253/32.1_BUD	240707_2.0009.156_BUD
157	2F09A3DE066148B0826646E3F1577F07	240707_2.0009.AR_3.253/32.2_BUD	240707_2.0009.157_BUD
158	DBAB89F7507F40289A3DE47EAAE773CB	240707_2.0009.AR_3.255/56.1_BUD	240707_2.0009.158_BUD
159	5E16B362BF9F4C02A314BFB4B0FDE408	240707_2.0009.AR_3.255/56.2_BUD	240707_2.0009.159_BUD
160	791AD4102572424E8D69B46E92B0DC53	240707_2.0009.AR_3.257/22.1_BUD	240707_2.0009.160_BUD
161	85E9E839E0A44A7EADF7E9CF3CECCFFD	240707_2.0009.AR_3.257/22.2_BUD	240707_2.0009.161_BUD
162	3B1F0F85D3534ABBA648A5DBC47D8708	240707_2.0009.AR_3.259/50.1_BUD	240707_2.0009.162_BUD
163	A372A576FB3044B2B5FB5E1477A11F33	240707_2.0009.AR_3.260/50.1_BUD	240707_2.0009.163_BUD
164	DF59E2391149489EB52D98D6BD5035A9	240707_2.0009.AR_3.260/50.2_BUD	240707_2.0009.164_BUD
165	E92A4463D23043848311FAE704A0A1F5	240707_2.0009.AR_3.260/50.3_BUD	240707_2.0009.165_BUD
166	571620E7EB8740849F20468D48EBF4DC	240707_2.0009.AR_3.260/50.4_BUD	240707_2.0009.166_BUD
167	D1CAB75E70194AB08E240137C0793BE0	240707_2.0009.AR_3.260/50.5_BUD	240707_2.0009.167_BUD
168	54323162CB8A4C4297FE15366F9FCF22	240707_2.0009.AR_3.267/11.1_BUD	240707_2.0009.168_BUD
169	3C0D1659CABE4166B2F59C3407463FAB	240707_2.0009.AR_3.267/11.2_BUD	240707_2.0009.169_BUD
170	AE4AB1C60B61447C8002A9C0632D9F39	240707_2.0009.AR_3.267/11.3_BUD	240707_2.0009.170_BUD
171	DB185954D147431BB35E5A9B68D65838	240707_2.0009.AR_3.267/11.4_BUD	240707_2.0009.171_BUD
172	43E174E5CC334A5AB6DAE181452E6F82	240707_2.0009.AR_3.269/20.1_BUD	240707_2.0009.172_BUD
173	B70138CE66734BB49D473FFD93220E44	240707_2.0009.AR_3.269/20.2_BUD	240707_2.0009.173_BUD
174	B73B2EAA71094284BDCD943797719057	240707_2.0009.AR_3.269/20.4_BUD	240707_2.0009.174_BUD
175	7E4A2C09FB044C7C9EEA5F99F345EAE3	240707_2.0009.AR_3.272/22.1_BUD	240707_2.0009.175_BUD
176	6FDDE341D5B940E699A37EFD606CBEDD	240707_2.0009.AR_3.272/22.3_BUD	240707_2.0009.176_BUD
177	35F85872C87E49989B2A9271234F8E39	240707_2.0009.AR_3.272/22.4_BUD	240707_2.0009.177_BUD
178	E3ED5986F9BA4EB7B84A1EBE6E6FFEC7	240707_2.0009.AR_3.272/22.5_BUD	240707_2.0009.178_BUD
179	531627E697224CC5B3903071668B090A	240707_2.0009.AR_3.283/35.1_BUD	240707_2.0009.179_BUD
180	ABFB2A7652D94C95ABA4FFF84EA17B3D	240707_2.0009.AR_3.284/35.1_BUD	240707_2.0009.180_BUD
181	E484C0A52C5B4ED9BC1CF95736A32AA5	240707_2.0009.AR_3.284/35.2_BUD	240707_2.0009.181_BUD
182	B9C5BD45F892455ABB949F569DF52ACD	240707_2.0009.AR_3.289/23.1_BUD	240707_2.0009.182_BUD
183	9FC1AEA63BE84FA0B9CB993B8AA50BB9	240707_2.0009.AR_3.290/23.1_BUD	240707_2.0009.183_BUD
184	EC88DCAB9B50433292A7050841D53EDA	240707_2.0009.AR_3.293/23.1_BUD	240707_2.0009.184_BUD
185	FD60762EFA6D48DD838B7A247E03E11F	240707_2.0009.AR_3.308/23.1_BUD	240707_2.0009.185_BUD
186	445F4DE676D24F258EDE2529DFF1846C	240707_2.0009.AR_3.312/11.1_BUD	240707_2.0009.186_BUD
187	E431E35AEF2549B1A79D0085B8777DC1	240707_2.0009.AR_4.119.1_BUD	240707_2.0009.187_BUD
188	C9618399D03A4C029A207481697BEEE8	240707_2.0009.AR_4.119.2_BUD	240707_2.0009.188_BUD
189	9C1672FD60674C5CACDF8E88371640A6	240707_2.0009.AR_4.119.3_BUD	240707_2.0009.189_BUD
190	5FFA1C651EB94A82B0C0A0858774030C	240707_2.0009.AR_4.119.4_BUD	240707_2.0009.190_BUD
191	05B84BF675BC463DB3327B081E31EEE1	240707_2.0009.AR_4.119.5_BUD	240707_2.0009.191_BUD
192	9F9EFFBE6A9E490880092A5A167BDD66	240707_2.0009.AR_4.120.1_BUD	240707_2.0009.192_BUD
193	71001E629B4B4ADF9695908D75E4AFA7	240707_2.0009.AR_4.120.2_BUD	240707_2.0009.193_BUD
194	1279D69EED14485AADD68027970F5F9A	240707_2.0009.AR_4.120.3_BUD	240707_2.0009.194_BUD
195	BB77435BE72D4D318E7523E001A0B87	240707_2.0009.AR_4.148/89.1_BUD	240707_2.0009.195_BUD
196	265765AE52FE4BBFB49A6963DDD1BE03	240707_2.0009.AR_4.148/89.2_BUD	240707_2.0009.196_BUD
197	BA404B6C09D44299BAC490E79783569F	240707_2.0009.AR_4.148/89.3_BUD	240707_2.0009.197_BUD
198	F115CE0AC0D14622A7EFA0F96C7372C3	240707_2.0009.AR_4.148/89.4_BUD	240707_2.0009.198_BUD
199	BAA00B04587046398D60E45EDB290B37	240707_2.0009.AR_4.150/90.1_BUD	240707_2.0009.199_BUD
200	A107F6F2298B4D2C49FA3530123462853	240707_2.0009.AR_4.162/121.1_BUD	240707_2.0009.200_BUD
201	4A05A623748E4020941281C0916D88C2	240707_2.0009.AR_4.162/121.2_BUD	240707_2.0009.201_BUD
202	DF312BCAE1C841F78E2BBD1829AB675F	240707_2.0009.AR_4.162/121.3_BUD	240707_2.0009.202_BUD
203	817E17BB542245F58A9B93AB1CB7498C	240707_2.0009.AR_4.162/121.4_BUD	240707_2.0009.203_BUD
204	9C0CAC53C6CD4ED99E27B9ADD8F4315E	240707_2.0009.AR_4.162/121.5_BUD	240707_2.0009.204_BUD
205	6798261B3C6246FA903ED1ECDE88003A	240707_2.0009.AR_4.162/121.6_BUD	240707_2.0009.205_BUD
206	AC455F1F646343AFA663997F2E1DDDB16	240707_2.0009.AR_4.165/121.1_BUD	240707_2.0009.206_BUD
207	3F11D49013554915ABF40EB781CEAAA7	240707_2.0009.AR_4.165/121.2_BUD	240707_2.0009.207_BUD
208	C71131D9856943DBB14DB713DC72A3A6	240707_2.0009.AR_4.165/121.3_BUD	240707_2.0009.208_BUD
209	A8D57DFF353C4306900DC10CE3B17DFB	240707_2.0009.AR_4.165/121.4_BUD	240707_2.0009.209_BUD
210	31F0958AC6CC41779B7296CE68C7ABC2	240707_2.0009.AR_4.165/121.5_BUD	240707_2.0009.210_BUD
211	252E6C3F500A4B169C0EA90211086578	240707_2.0009.AR_4.165/121.6_BUD	240707_2.0009.211_BUD
212	70C1107AB51743F6A16D12971BCBAC57	240707_2.0009.AR_4.165/121.7_BUD	240707_2.0009.212_BUD
213	E5DF16B752DD4A71AFDC2DAB5985C8EE	240707_2.0009.AR_4.165/121.8_BUD	240707_2.0009.213_BUD
214	CE684579E62C4966BE3D0D731304EC70	240707_2.0009.AR_4.165/121.9_BUD	240707_2.0009.214_BUD
215	8F10D3D90D474544A587426F79EC22C5	240707_2.0009.AR_4.165/121.10_BUD	240707_2.0009.215_BUD
216	987E74F292DE483C8E31D4301AFD6423	240707_2.0009.AR_4.189/101.1_BUD	240707_2.0009.216_BUD
217	7178B56772A340AFB6AD4550C4A2C908	240707_2.0009.AR_4.189/101.2_BUD	240707_2.0009.217_BUD
218	63FD2769D239400C83EFDAF4A561C735	240707_2.0009.AR_4.189/101.3_BUD	240707_2.0009.218_BUD
219	DA312C150EC342C28027753CBC4CC001	240707_2.0009.AR_4.189/101.4_BUD	240707_2.0009.219_BUD
220	F7E1F63FED4541D8B44DBB9D470FA944	240707_2.0009.AR_4.323/101.1_BUD	240707_2.0009.220_BUD
221	518B882E61A34E09A07537B3C9CB5D0C	240707_2.0009.AR_4.323/101.2_BUD	240707_2.0009.221_BUD
222	66951EB2944848249E42FEAB026B5F5B	240707_2.0009.AR_4.323/101.3_BUD	240707_2.0009.222_BUD
223	E99019F84292484D9EE1D8F3439D685F	240707_2.0009.AR_4.323/101.4_BUD	240707_2.0009.223_BUD
224	B8D6C6E437AF4D2F99B3A583488E47E0	240707_2.0009.AR_4.338/101.1_BUD	240707_2.0009.224_BUD
225	7AAE3B30AE39493BB13E29DD35F8F1D5	240707_2.0009.AR_4.338/101.2_BUD	240707_2.0009.225_BUD

226	B4DC221B1EE84EF5B0EFFD7C9CFE90AE	240707_2.0009.AR_4.338/101.3_BUD	240707_2.0009.226_BUD
227	749CBD3429DC4C06A76A5A92EB0A3F69	240707_2.0009.AR_4.346/14.1_BUD	240707_2.0009.227_BUD
228	4AD1D85F9CE040E286BD010540EB49E9	240707_2.0009.AR_4.346/14.2_BUD	240707_2.0009.228_BUD
229	B9C76B83C2E141CAA7CC12C2BAEAF899	240707_2.0009.AR_4.348/34.1_BUD	240707_2.0009.229_BUD
230	C4DCB5E9C83E45949D8923D23B91C50C	240707_2.0009.AR_4.348/34.2_BUD	240707_2.0009.230_BUD
231	0615C3A12C864356ACF7D227B4DD08AD	240707_2.0009.AR_4.348/34.3_BUD	240707_2.0009.231_BUD
232	DA09AEFA26654C9F9D89974B3E0B1B0F	240707_2.0009.AR_4.348/34.4_BUD	240707_2.0009.232_BUD
233	D1E8CC4FDD134BFAB45747A302DF279A	240707_2.0009.AR_4.348/34.5_BUD	240707_2.0009.233_BUD
234	3E817370E1644A18A4D8796AC9BF3793	240707_2.0009.AR_4.349/13.1_BUD	240707_2.0009.234_BUD
235	2CBD0597EAD74FEE9EA0ED8C97F6BCDB	240707_2.0009.AR_4.349/13.2_BUD	240707_2.0009.235_BUD
236	807D7A976B6D4920AD1FBE38824C5ED2	240707_2.0009.AR_4.349/13.3_BUD	240707_2.0009.236_BUD
237	6A74DFEAB0F740EFB6786C01B182E8ED	240707_2.0009.AR_4.349/36.1_BUD	240707_2.0009.237_BUD
238	3A2645834C6543E6AE1D5A1F5AD6DA71	240707_2.0009.AR_4.349/36.2_BUD	240707_2.0009.238_BUD
239	CC830B04D41845EE86C877C3DE56BFE7	240707_2.0009.AR_4.349/36.3_BUD	240707_2.0009.239_BUD
240	EE5E314FBAC748399191C6E03570A365	240707_2.0009.AR_4.349/36.4_BUD	240707_2.0009.240_BUD
241	A2567093B83A4B738CC8224A6E24A696	240707_2.0009.AR_4.350/13.1_BUD	240707_2.0009.241_BUD
242	20E068B9ED9145D2885E102FF2AB8D76	240707_2.0009.AR_4.350/13.2_BUD	240707_2.0009.242_BUD
243	F66DC8EC8B83481DA2A7183DD6601DF9	240707_2.0009.AR_4.350/13.3_BUD	240707_2.0009.243_BUD
244	B2000D0ACD4A4E278DBE1B041FDA3072	240707_2.0009.AR_4.350/13.4_BUD	240707_2.0009.244_BUD
245	ABAE2ED6B2FD410584B3B8FECA33D037	240707_2.0009.AR_4.351/15.1_BUD	240707_2.0009.245_BUD
246	C38D7ED61C78444EBD2B2F2124E25EA8	240707_2.0009.AR_4.351/15.2_BUD	240707_2.0009.246_BUD
247	78DE00D6B8704581B8348231FE674A28	240707_2.0009.AR_4.352/90.1_BUD	240707_2.0009.247_BUD
248	8351D2ED455045869F08146B015AD6BF	240707_2.0009.AR_4.352/90.2_BUD	240707_2.0009.248_BUD
249	1B766E549C2649A69D991D6D614343FA	240707_2.0009.AR_4.352/90.3_BUD	240707_2.0009.249_BUD
250	8A622DAC7D2640E9B900914237CAE675	240707_2.0009.AR_4.352/90.4_BUD	240707_2.0009.250_BUD
251	89D055E43F494994BD4357FA332751AB	240707_2.0009.AR_4.352/90.5_BUD	240707_2.0009.251_BUD
252	3B34F3AE339D4052A8E1DA93DFA59952	240707_2.0009.AR_4.353/11.1_BUD	240707_2.0009.252_BUD
253	522E3290C93B446A8547BB62ABA62935	240707_2.0009.AR_4.353/11.2_BUD	240707_2.0009.253_BUD
254	179899FA58E346A3A238857BF1D5DBAF	240707_2.0009.AR_4.354/11.1_BUD	240707_2.0009.254_BUD
255	2005F28249714739B0D0B4FFADEB5794	240707_2.0009.AR_4.354/11.2_BUD	240707_2.0009.255_BUD
256	59337C7C4BD448FB851B513A0B1AD62F	240707_2.0009.AR_4.361/15.1_BUD	240707_2.0009.256_BUD
257	8A72C596A70E44C59233634C1F9541D8	240707_2.0009.AR_4.361/15.2_BUD	240707_2.0009.257_BUD
258	C4F637A4A696417B9FFE2F2399E77550	240707_2.0009.AR_4.363/101.1_BUD	240707_2.0009.258_BUD
259	8563D5AE095D489B959A41A73F3595E9	240707_2.0009.AR_4.363/101.2_BUD	240707_2.0009.259_BUD
260	BF4FDAF730E44A1FBB9F8788D2ABF760	240707_2.0009.AR_4.366/94.1_BUD	240707_2.0009.260_BUD
261	3FE77DDAA0AC420E9D6D1EBE86096156	240707_2.0009.AR_4.366/94.2_BUD	240707_2.0009.261_BUD
262	B309CFFE23014C628BD1F772B6BF7472	240707_2.0009.AR_4.366/94.3_BUD	240707_2.0009.262_BUD
263	E1C3413980A245AB879A8241D46A55B9	240707_2.0009.AR_4.366/94.4_BUD	240707_2.0009.263_BUD
264	25E965E84EB04DC1B47AE21A17BDC116	240707_2.0009.AR_4.385/101.1_BUD	240707_2.0009.264_BUD
265	950E1723D45A4C1BBB71B1EE8095F7FC	240707_2.0009.AR_4.385/101.2_BUD	240707_2.0009.265_BUD
266	6732C48025A542F8BC408154CD7C5B5C	240707_2.0009.AR_4.385/101.3_BUD	240707_2.0009.266_BUD
267	715A48AA31C540F19217C257268B5CFF	240707_2.0009.AR_4.398/101.1_BUD	240707_2.0009.267_BUD
268	5E04D3389EA24B7D8990CE478CB0BF5F	240707_2.0009.AR_4.398/101.2_BUD	240707_2.0009.268_BUD
269	9CAFB703540449098D556D2B7F4A158A	240707_2.0009.AR_4.398/101.3_BUD	240707_2.0009.269_BUD
270	321C2D283A39491A8BC4D729B5D968ED	240707_2.0009.AR_4.398/101.4_BUD	240707_2.0009.270_BUD
271	A67DBB70FE284DD8B93C8E92C0722A95	240707_2.0009.AR_4.398/101.5_BUD	240707_2.0009.271_BUD
272	479365E456D9402B847E048EFF72F5FF	240707_2.0009.AR_4.410/101.1_BUD	240707_2.0009.272_BUD
273	295D5C8C45134245B326E118A6D707DB	240707_2.0009.AR_4.411/101.1_BUD	240707_2.0009.273_BUD
274	FE0D713D4D264051A9B28244EFA7AD6D	240707_2.0009.AR_4.411/101.2_BUD	240707_2.0009.274_BUD
275	7204B2CDA1B24308A88DEBA859FFDA40	240707_2.0009.AR_4.411/101.3_BUD	240707_2.0009.275_BUD
276	FF2C366A24D2441D96EB2C88A0733B99	240707_2.0009.AR_4.411/101.4_BUD	240707_2.0009.276_BUD
277	5FA13B2646234BABA39380BC5E5C98D1	240707_2.0009.AR_4.425/101.1_BUD	240707_2.0009.277_BUD
278	1426F8AFAB684FE9A44D5E52355704D0	240707_2.0009.AR_4.427/126.1_BUD	240707_2.0009.278_BUD
279	7CBD43A4847649F4A35AD2E4066D798B	240707_2.0009.AR_4.427/126.2_BUD	240707_2.0009.279_BUD
280	216675CDF0EB4484AF6ECAFBBA995E95	240707_2.0009.AR_4.427/126.3_BUD	240707_2.0009.280_BUD
281	8813CB17C6FC4DBEBD7FE572F949FE4A	240707_2.0009.AR_4.427/126.4_BUD	240707_2.0009.281_BUD
282	F3512767942F4549840334FAC5CC84F	240707_2.0009.AR_4.434/34.1_BUD	240707_2.0009.282_BUD
283	2560CEFFD1814E5BB9A6DE82E381C224	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/6.2_BUD	240707_2.0009.283_BUD
284	58754FE8DE6B44E8A3C0E37161970191	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/7.1_BUD	240707_2.0009.284_BUD
285	BFB23D5C5C7C4C27BB1E1EB5B23A9F0F	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/9.1_BUD	240707_2.0009.285_BUD
286	D12DDADF677F4F6A8990E042C854A5C7	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/11.1_BUD	240707_2.0009.286_BUD
287	0D62B48921424B54AFA624F1C61CC057	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/11.2_BUD	240707_2.0009.287_BUD
288	83FDF18A6FE54999AA3820D9A2A1940B	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/12.1_BUD	240707_2.0009.288_BUD
289	C5C8EFCFDEE44966876708265F756A98	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/12.2_BUD	240707_2.0009.289_BUD
290	ADD2E9AB778E42D582EB6741D5D858FC	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/14.1_BUD	240707_2.0009.290_BUD
291	E898DDAB3D654FFFBABEB3A8BB71303DE	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/14.2_BUD	240707_2.0009.291_BUD
292	A25109D0D7154EA98EF69E5475F8B1C4	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/15.1_BUD	240707_2.0009.292_BUD
293	CBAC8073F2B54A2BB973D4B22967C235	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/15.2_BUD	240707_2.0009.293_BUD
294	57FCB9A2C5104F9E86BB258AE064C1E3	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/16.1_BUD	240707_2.0009.294_BUD
295	C56F73553571433D930C6B2E8BBEC62F	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/24.1_BUD	240707_2.0009.295_BUD
296	624FCEE9A40A4449A9ACC4C9BAADAD2A	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/25.1_BUD	240707_2.0009.296_BUD
297	71D3C45648D641D8A8DB93FC25D70DA8	240707_2.0009.AR_PGRSKRZYDŁOWICE.275/57.1_BUD	240707_2.0009.297_BUD
298	2CE09FB21FCD459199BE8711C0CA94AF	240707_2.0009.AR_PGRSKRZYDŁOWICE.275/57.2_BUD	240707_2.0009.298_BUD
299	6E5E1F36EBF04D64B18F51B88165D96B	240707_2.0009.AR_PGRSKRZYDŁOWICE.276/57.1_BUD	240707_2.0009.299_BUD
300	961F424A0F1D4BCA83477FCA66D28A4	240707_2.0009.AR_PGRSKRZYDŁOWICE.279/57.1_BUD	240707_2.0009.300_BUD
301	F3C2622712434357AF390E884E097B87	240707_2.0009.AR_PGRSKRZYDŁOWICE.280/57.1_BUD	240707_2.0009.301_BUD
302	D1AAEFB6364B4C50A21C3D746ADBAB47	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.1_BUD	240707_2.0009.302_BUD
303	5817EAC6B15B47738C9EDCF72D9E5947	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.2_BUD	240707_2.0009.303_BUD

304	FA977BEE357B4BCCA9419D3E2A3CB984	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.3_BUD	240707_2.0009.304_BUD
305	2ACDD2F18B0442A482787FFC794AB644	240707_2.0009.AR_PGRSKRZYDŁOWICE.328/60.1_BUD	240707_2.0009.305_BUD

Raport lokali z przenumerowaych budynków.

Lp.	Identyfikator	Stary IG5	Nowy IG5
306	745E1F91369D4868AB13328BD509A324	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/12.1_BUD.1_LOK	240707_2.0009.288_BUD.1_LOK
307	21C68822AFE744D69D578EC8820CC603	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/12.1_BUD.2_LOK	240707_2.0009.288_BUD.2_LOK
308	AE2D5E4D94724022B75E4B30C8DC8408	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/15.1_BUD.1_LOK	240707_2.0009.292_BUD.1_LOK
309	EE5B6A5A2B624ECE886325CC2CAA4A6C	240707_2.0009.AR_PGRSKRZYDŁOWICE.8/15.1_BUD.2_LOK	240707_2.0009.292_BUD.2_LOK
310	06DBD67815DC44AFBC3ADB0388769678	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.1_BUD.1_LOK	240707_2.0009.302_BUD.1_LOK
311	011B7130377F4297A2E159C7FE95D4BE	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.1_BUD.2_LOK	240707_2.0009.302_BUD.2_LOK
312	776F2CAC76CC47FA9A342D234E85006F	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.1_BUD.3_LOK	240707_2.0009.302_BUD.3_LOK
313	D0E0EDA7B81B4325B8DE6F47A8F1A115	240707_2.0009.AR_PGRSKRZYDŁOWICE.283/57.1_BUD.4_LOK	240707_2.0009.302_BUD.4_LOK